History of original corner establishments

Unsurveyed - subdivided section.

11	AGRA	141		
T	55.	R.	33	B∳E.
NE	1/16		s	11

No record of subsequent remonumentation found in County Records.

Description of corner evicence found:

None.

Dractiption of monument and accessories I established to perpetuate the or ginal location of this corner

Set $2\frac{1}{2}$ " x 30" iron pipe 22" in ground with brass cap as shown: from which I scribed Bearing Trees.

A fir 8" diameter bears South $30^{\circ}18$ ' West 5.85 feet marked NE 1/16 S 11 BT A fir 8" diameter bears South $01^{\circ}39$ ' West 32.00 feet marked NE 1/16 S 11 BT

I nailed a brass washer marked PLS 933 to the BT blaze of both trees. Set steel fence post 5 feet East of corner. The corner is 1 foot East of Morth-South fence and is 13 feet South of fence corner of fences running North and East. Used T-2 and steel tape, measuring a horizontal distance to center of Bearing Trees.

PROFESSIONAL
AND SURVEYOR

OREGON
DAVID H. KRUMBEN

T 5S. R. 33\{E.\

NE 1/16 S 11

1978

PLS 933

Office of County Surveyor County of Umatilla

State of Oregon I hereby certify that the within Instrument was filed in this off :e
for record on the Ocy of OCOUNTY OFFICIALLY

(COUNTY OFFICIALLY)

F-20

GPO 796-333

Form R6-71 10-57 (9/71)