USDA-FOREST SERVICE	
Index G-17	CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No
T <u>5S</u> R. <u>33½E</u>	R.D. <u>Ukiah</u> County <u>Umatilla</u>
MeridWillamette	N.F. Umatilla State Oregon
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
Sec 11	None DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND None
6	
PHOTO IDENTIFICATION DATA	
Photo No.	
Filed At.	3
Object Ident.	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Ident. By	
PLANE COORDINATE POSITION DATA State Zone X Y Estab. By Agency 8	From intersection of Roads S552 and S534, which is about 700 feet West of Frazier Guard Station, go South on Road S534 about 3/4 mile to a jeep road to the right. Follow it for about ½ mile. The corner is South of the road 9.3 chains in density trees.
Teny C. Manby	Title 0 Division S. Headquarters 8/78 7100-52 (3/68)

.

CORNER RECORD (PERPETUATION)

Set $2\frac{1}{2}$ " x 30" iron pipe with brass cap (stamped) Pipe is 15" in ground with stone mound raised to within 3" of top. \$ 10 | \$ 11 1978 PLS 933

T 5S R 33 €E

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE Fir 10" diameter bears North 56⁰51' West 13.65 feet with sign 54-3 and 54-5 on tree. Fir 8'' diameter bears South 85⁰35' East 33.00 feet with sign 54-3 and 54-4 on tree.

Set steel post 3 feet North with sign 54-4 painted red band around trees.

Work Done By. T. Hamby Title Surveyor Date 7/19/78 State Registration No. 0.P.L.S. 1638

Certified Cor. Record Prepared ? Yes X No Filed At: Umatilla County Surveyor Date 8-8-78 II

REMARKS

Witness by Richard Barton and William Hampton.

.

Index File No. T. R.

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

M.

Tract or Surv. No.

Cor.

13