


History of original corner establishment:

Unsurveyed - subdivided section.



No record of subsequent remonumentation found in County Records.

Description of corner evidence found:



None.

Description of monument and accessories established to perpetuate the original location of this corner

Set 2 1/2" x 30" iron pipe 24" in ground with brass cap marked as shown: from which I scribed Bearing Trees.

A fir 9" diameter bears South 84°25' West 17.50 feet marked C 1/4 S 11 BT
A tamarack 22" diameter bears South 17°12' West 27.20 feet marked C 1/4 S 11 BT

I nailed a brass washer marked PLS 933 to the BT blaze of both trees. Set a steel fence post 3 feet East of corner. Corner is 140 feet South of a road which runs Northeast by Southwest. Used T-2 and steel tape, measuring a horizontal distance to center of Bearing Trees.



Office of County Surveyor County of Umatilla
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the day of
..... by
(COUNTY OFFICIAL) (DEPUTY)

G-19