

7-31-01

LAND CORNER RECORD

GRANTOR/SURVEYOR/PUBLIC OFFICER: This corner record correctly represents work performed by me or under my direction in conformance with the Survey Recording Act.

COMPANY OR AGENCY:

William R. Wells Land Surveying

ADDRESS:

P.O. Box 1696 357 NE Hwy. 11 Pendleton, OR 97801

REGISTERED PROFESSIONAL LAND SURVEYOR

Will: R. Wells

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

renews 6-30-02 7/31/01

GRANTEE: PUBLIC

LEGAL: TWP:

SEAL/SIGNATURE/DATE CORNER CODE: A-1

ADDITIONAL IDENTIFIER: (BLM designation, street or plat names, block, lot, etc.)

NORTHWEST CORNER OF SECTION 6.

COUNTY: Walla Walla

OREGON PLANE COORDINATES: N: 868431.69 E: 8616507.36, (inf ORN 83/91)

ORDER:

CORNER INFORMATION: Discuss the history, evidence found, and perpetuation of the corner. Diagram the references; provide the date of work; and, if applicable, a reference to a map of record and/or the field book/page no. Use the back, if needed.

RGE: 32E

A. Most recent approved record is resurvey by Edwin Richard, under Special Instructions dated February 22, 1867. Record states: Intersect mound with trench and pits but without post, in which I set a new post for corner to Townships 6 & 7 North, Ranges 31 & 32 East. Continued on back......

2. EVIDENCE FOUND:

Fence corner with fences extending North-South and West.

3. PERPETUATION INFORMATION:

At the East side of said fence corner set a 2 1/4" brass cap on a 1" x 30" galvanized iron pipe 6" below ground level. Cap is marked:

T7N R31E R32E S36 | S31 S1 | S6 T6N 2001 OPLS 1106 WPLS 17372

From which:

A brass washer stamped "PLS 1106", 4" above ground level in North side of fence post bears S 01° E, 53.7 feet. A brass washer stamped "PLS 1106", 4" above ground level on West side of South end of H brace bears N 01° W, 16.2 feet. Set steel fence post 1.0 Feet South of brass cap. Compass declination 18°East.

This form is in compliance with the intent of RCW 65.04.045 and prescribed by the Public Land Survey Office, Department of Natural Resources - 1/97. \6N32A1ORN

RECEIVED BY

Umatilla County Surveyor