UMATILLA County

T 06N, R 35E., W.M. Segregated Surveys:

Corner Code No. Z-15

Name: SOUTH 1/4 CORNER SEC. 34

Corner No .: DLC, HES, Tract, Mining Claim, Indian Allotment, Federal

1. History of Corner Establishment and Subsequent Restoration: CORNER WAS ORIGINALLY ESTABLISHED UNDER GLO CONTRACT 110 BY ODELL AND LEWIS AS A POST, STONE MOUND, AND CHARRED STAKE. THERE IS NO FURTHER RECORDS FOR THIS CORNER.

2. Description of Evidence Found:

NONE. CORNER SET USING SINGLE PROPORTIONATE METHOD BETWEEN THE SOUTHWEST CORNER OF SECTION 33 AND THE SOUTHEAST CORNER OF SECTION 34, OFFSETTING FOR LATITUDINAL CURVE AS PER BLM INSTRUCTIONS.

3. Describe Monument, Accessories, and Corollary Data to Perpetuate this Corner Location. Diagram corner, indicate meridian and reference to map of Record. Surveyor's Field Book No. Page No. Date of Work 10/21/91 TACK & BRASS WASHER TYPILAL LI: NS4-21E 4210 IN CEAD PLUE IN CONCRETE 42:533-10E 5/4 CANAL 43: 510-26W 7067 C4: N2-02W 254 49 A. 2"BRASS CAP IN CONCRETE IN MON. CASE STAMPED R35 E LS 2360 1991 Oregon Plane Coordinates: North Zone, Y Order Accuracy. Derived From: REGISTERED Pin Pointed on Photo No. Date Located at PROFESSIONAL LAND SURVEYOR SURVEYOR'S CERTIFICATE This corner record correctly represents work performed by me or under my direction in OREGON compliance with the provisions of the laws of JULY 26, 1988 PAUL W. P. TOMKINS the State of Oregon. 2360 Signature Certificate No. 2360

AUDITOR'S CERTIFICATE Filed for record this day of , 19... at M. in Book at Page at the request of

> RECEIVED BY Umatilla County Surveyor Rec'd By

UMATILLA County

Γ	06N,	R	35E.	,	W.M.	
betenerned		SHYUNG'				

Corner Code No. Z-15

J.,	ODIY, K	SSE.	,	W	- 11	
Se	areasted	Surve	V	:		

Name: SOUTH 1/4 CORNER SEC. 34

Corner No .: DLC, HES, Tract, Mining Claim, Indian Allotment, Federal

1. History of Corner Establishment and Subsequent Restoration: CORNER WAS ORIGINALLY ESTABLISHED UNDER GLO CONTRACT 110 BY ODELL AND LEWIS AS A POST, STONE MOUND, AND CHARRED STAKE. THERE IS NO FURTHER RECORDS FOR THIS CORNER.

Description of Evidence Found:

RECEIVED BY Umatilla County Surveyor

NONE. CORNER SET USING SINGLE PROPORTIONATE METHOD BETWEEN THE SOUTHWEST CORNER OF SECTION 33 AND THE SOUTHEAST CORNER OF SECTION 34, OFFSETTING FOR LATITUDINAL CURVE AS PER BLM INSTRUCTIONS.

3. Describe Monument, Accessories, and Corollary Data to Perpetuate this Corner Location. Diagram corner, indicate meridian and reference to map of Record. Surveyor's Field Book No. Page No. Date of Work 10/21/91 TACK & BRASS WASHED TYPICAL 11: NS4-21E 4210 IN CEAD PLUE IN 62=533-10E 5/4 CONCRETE CANAL 43: 510-26W 706] C4: N2-02W 254 49 A. Z"BRASS CAP IN CONCRETE IN MUN. CASE STAMPED PAUED €35 E TEN 5.34 T5N 5.3 LS 2360 1991 Oregon Plane Coordinates: North Zone, Y Order Accuracy. Derived From: REGISTERED Pin Pointed on Photo No. Date Located at PROFESSIONAL LAND SURVEYOR SURVEYOR'S CERTIFICATE This corner record correctly represents work performed by me or under my direction in OREGON compliance with the provisions of the laws of PAUL W. P. TOMKINS the State of Oregon. 2360 Signature Certificate No. 2360 AUDITOR'S CERTIFICATE

Filed for record this day of , 19... at M. in Book of at Page at the request of