GOVERNMENT CORNER RECORD

| Township 6N Range 35E Section 35 | County_UMATILLA |
|---|--|
| State OREGON Date 10/1/96 Number Z-20 | |
| Corner Designation: EAST 1/16 CORNER SECTIONS 2 T6N, R35E AND T5N, R35E Previous Renewals Monument (s) Found: (Condition and Source) | Condition Report Only Not Found Renewed Surveyed In X Referenced |
| FOUND 5/8" REBAR (NO CAP) .15' BELOW PAVEMENT SURFACE. | MONUMENT DETAIL x Found Set |
| Accessories Found: 5/8" REBAR & CAP (TOMKINS SURVEYING) 37.97' N.W. NAIL AND BRASS WASHER IN POWER POLE 21.18' S.E. | NO DETAIL AVAILABLE |
| Monument & Accessories Set (Procedure and Description) SET CAP ON EXISTING REBAR MONUMENT. | |
| SET P.K. NAIL & ALUMINUM TAGS ON POWER POLES 62.60' N. TIED TO TOP OF FIRE HYDRANT 65.39' N.E. (SEE SKETCH DETAIL BELOW) | W. AND 75.53' S.W. |
| Sketch of Monument, Accessories and General A | rea Surveyor's Seal |

