## OREGON CORNER RESTORATION FORM

COUNTY: Umatilla. DATE: 07/29/08

CORNER DESIGNATION: J-5, The Northeast Corner of Section 18, Township 6 North, Range 36 East, W.M..

PREVIOUS RENEWALS/SURVEYS ETC: Corner originally set by Odell & Lewis under GLO Contract No. 110, dated February 7, 1865. Notes state: Set post Cor. for fractional Secs. 17 & 18. Drove charred stake; dug pits & raised mound, as per instructions.

MONUMENT AND ACCESSORIES FOUND: None. Corner falls in State line Road.

MONUMENT MARKING DETAIL:

T6N R36E <u>\$18</u> WA \$18|\$17 OR CC 2008 PLS 1106

MONUMENT SET: Reestablished corner position by single proportionate measure, on the parallel of latitude, between recovered State Line Mileposts 29.0 and 30.0. At the reestablished corner position, in paved State Line Road, set a 2" brass cap on a copper 12" clad bar, with cap ½" below paved road surface and surrounded with grout. Cap is marked as shown in "Monument Marking Detail".

New accessories:

A 5/8" x 24" rebar with a red plastic cap marked "OR PLS 1106, WA PLS 17372", bears North 58° East, 32.9 feet.

A 3/4" brass washer stamped "PLS 1106", on a high tension power pole, 1' above ground level, bears South 76 1/2° East, 138.1 feet, with bearing object and witness sign attached to pole. A 5/8" x 24" rebar with a red plastic cap marked "OR PLS 1106, WA PLS 17372", bears South 46° West, 22.6 feet.

A  $5/8" \times 24"$  rebar with a red plastic cap marked "OR PLS 1106, WA PLS 17372", bears North  $37^{\circ}$  West, 26.7 feet.

Attached bearing object signs to all rebar accessories.

LOCATION AND COMMENTS: Corner is located 3 South of yellow stripe on State Line Road.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 858210.05E = 8748229.70

FIRM: Wells Surveying P.O. Box 1696 Pendleton, OR 97801

COMPASS DECLINATION: 18° East

Surveyor's Seal

Witnesses: Jason Wells, LSIT

\6N36J5

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

Renews 6-30-10

09-10-C