## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established in 1881 by Meldrum & Campbell under General Land Office Contract No. 380.

Surveyor General Record States:

Set post for \$ cor. From which:

A 20" Pine bears N 79 W, 56 lks. A 28" Pine bears East, 23 lks. T 6S
R 29E | R 30E
S 13 | S 18

No record of subsequent remonumentation was found in County Records.

Description of corner evidence found:

Found small mound of stone, from which:

Original BTs

A 24" Pine snag bears N71W, 37.0 ft., scribes visable. A 10" Pine, dead and down, bears East, 15.2 ft., scribes visable.

Description of monument and accessories I established to perpetuate the original location of this corner

At corner point, I set 22"x30" iron pipe, with brass cap marked as shown, 24" in ground from which:

New BTs

A 12" Fir bears N43E, 22.0 ft. marked  $\frac{1}{4}$ S18 T6S R30E BT. A 10" Pine bears S72W, 58.5 ft. marked  $\frac{1}{4}$ S13 T6S R29E BT.

Nailed brass washer to BT blaze. Set steel fence post 5+ ft. East and 5+ ft. North. Used steel tape and magnetic compass with 20° E declination. Measured to face of blaze on original BTs and center of new BTs.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 10, 1854 DUANE I. GRIFFITH 644

country of distanting Country of distanting Country of distanting

(DEPUTY)

いし

Form R6-7100-57 (9/66)

22

S-58-M

T 68

PLS 644

R 29E

S 13

R 30E

S 18