CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by Meldrum and Campbell under General Land Office Contract No. 380.

Surveyor General Records states: Set post for cor. to sections 13, 18, 19, 24 from

which:

A Pine 15 in. dia. bears N 31° W, 110 lks. dist. A pine 30 in. dia. bears S 50° W, 34 lks. dist. A Fir 24 in. dia. bears S 81° E, 53 lks. dist. A Pine 18 in. dia. bears N 41° E, 113 lks. dist.

Di	AGR/	46				
	T	6	S			
R	29	Е	R	30	E	
13			18			
	2	+	19			

No record of subsequent remonumentation was found in county records. Description of corner evidence found:

Found SW BT, dead and down stump, dim BT only. Found no evidence of other BTs.

(See map of Survey, dated December, 1975)
Description of monument and accessories I established to perpetuate the original location of this corner

At record bearing and distance from SW BT I set 2 1/2" X 30" iron pipe with brass cap marked as shown 25" in ground, from which:

A 14" Fir bears N 44° E, 63.9 ft. marked T6S R30E S18 BT. A 12" Pine bears S 16° E, 14.9 ft. marked T6S R30E S19 BT. A 14" Fir bears S 27° W, 26.7 ft. marked T6S R29E S24 BT. A 10" Pine bears N 45° W, 14.0 ft. marked T6S R29E S13 BT

Set steel fence post 5+ ft. West.

R 29 E R 30 E S 13 S 18 S 24 S 19 1975 S 644 PLS

OREGON DUANE I GSFFITH

REGISTURED

PROFESSIONAL AND SURVEYOR

> Brass Washer nailed to BT blazes. Used steel tape and magnetic compass with 19° 30' East declination. Measured to center of all BTs.

..... County of , I hereby certify that the within Instrument was filed in this office

5-58-R

Form R6-7100-57 (9/71)

☆ GPO 796-333