CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established in 1881 by Meldrum & Campbell under General Land Office Contract No. 380.

Surveyor General Record States:

Set post for cor. to sect's 25-30-31-36. From which:

A 27" Fir bears N 61-30 W, 32 lks.

A 20" Pine bears S 29 E, 29 1ks.

A 30" Pine bears S 34 W, A 10" Fir bears N 31 E, 30 lks.

59 1ks.

DIAGRAM T. 68 R 29E | R 30E

No record of subsequent remonumentation was found in County Records. Description of corner evidence found:

Found original BTs as follows:

A 42" Fir, good condition, bears N61W, 21.1 ft., blaze healed.

A 24" Fir, good condition, bears N31E, 38.9 ft., blaze healed.

No evidence of other BTs.

Description of monument and accessories I established to perpetuate the original location of this corner

At corner position, I set $2\frac{1}{2}$ "x30" iron pipe with brass cap marked as shown, 22" in ground, raised mound of stone 7 ft. at base to top of cap, from which:

New BTs

A 16" Fir bears S39E, 37.7 ft. marked T6S R30E S31 BT. A' 8" Fir bears S44W, 83.1 ft. marked T6S R30E S36 BT.

Nailed brass washer to BT blaze. Set steel fence posts 5+ ft. North and 5+ ft. West of corner. Used steel tape and magnetic compass with 20° E declination. Measured to face of blaze on original BTs and center of new BTs.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGOM JULY 10. 1254 DUANE I. GRIFFITH

T 68

s 36 | S 31 1974

R 29E

, R 30E