```
USDA-FOREST SERVICE
 Index
                                             CORNER RECORD (SEARCH)
                                                                        Tract or
                                                                                         Cor.
File No. A-13
                                             Sef. FSM 7151.4
                                                                       Survey No
                                                                                         No.
TSS
                  R30E
                                            North Fork John Day
                                                                       County. Umatilla
Merid.
         Willamette
                                    N.F.
                                             Umatilla :
                                                                       State
                                                                                Gregon
                        759R30E
Corner Diagram
                                    1 Describs corner monument found
                                    1 Steel pipe extending 15" above the ground with a 2 1/2" brass cap stamped as
                           533
                        54 | 53
                                    l shown in the diagram. Monument is in a stone mound.
                        T691R30E
                          00
                          1976
                        OPLS 598
Photo Identification Data
                                   l Describe bearing trees or other official accessories found
Photo No.
                                   I A dead and down Lodgepole Pine bears N36°W, 13.0' scribed T5S in a weathered
filed at
                                  l blaze. A 24" Ponderosa Pine stump bears $18°E, 36.0' scribed E3.
Object Ident.
                                   1 A 10" Douglas Fir bears S61°E, 74.4' with healed scribe.
Ident. by
                                  1 A 15" Ponderosa Pine bears $31°W, 52.2' with healed scribe.
                 Signature
Plane Coordinate Position Data
                                   l Describe corner location relative to near-by features, also how to reach corner
State
                                  ! From the junction of roads 5312 and 5320, follow road 5320 east 0.5 miles to
                 Zone
                                   l road 5220100. Follow road 5320100 south 0.6 miles to an east-west fence line.
                                   1 Follow this fence line east approximately 0.3 miles. The corner is located
Estab. by
                                   l approximately 50' north of this fence line.
                 Agency
        Signature
                        Title
                                           Division
                                                            Headquarters
  David L. Hadolock Land Surveyor
                                                                                       Date
                                                                                                  7100.52
                                                            Pendleton, QB
                                                                                       June 1988
```

	CORNER RECORD (PE	FFE (UA) LUN)		
X		Х		
Monument:Describe new monument set, or wor	k done to preserve e	existing monument		
Set 30" aluminum pipe 17" in the ground at				
section line from the south. Stamped the 2 1/2" alumin				533
Built a stone mound around the monument. T				
monument. Set a steel fence post 5' east o				
Monument and Property Boundary signs. Stam				CC
Х			. у	PLS 852
Accessories: Describe new BT's witness obje	cts of costablished	l av wark dang ta procor	a	
		,, p		
Used old bearing trees as bearing trees for respect to the new monument. The 10" Dougl				
respect to the new monument. The 10" Dougl S31°00'W, 54.1'. Attached Forest Service L repainted red bands and blazes on all of t	as Fir bears S57°15' and Survey Monument he trees.	E, 75.6'. The 15" Ponde and Bearing Tree signs	rosa Pine bears to these trees a	
respect to the new monument. The 10" Dougl S31°00'W, 54.1'. Attached Forest Service L repainted red bands and blazes on all of t x	as Fir bears S57°15' and Survey Monument he trees.	E, 75.6'. The 15" Ponde and Bearing Tree signs	rosa Pine bears to these trees a State Regis	tration No.
respect to the new monument. The 10" Dougl S31°00'W, 54.1'. Attached Forest Service L repainted red bands and blazes on all of t x	as Fir bears S57°15' and Survey Monument he trees Land Surveyor	E, 75.6'. The 15" Ponde and Bearing Tree signs X Date Nov 1988	rosa Pine bears to these trees a State Regis or Agency	tration No. 852
respect to the new monument. The 10" Dougl S31°00'W, 54.1'. Attached Forest Service L repainted red bands and blazes on all of t x	as Fir bears S57°15' and Survey Monument he trees Land Surveyor	E, 75.6'. The 15" Ponde and Bearing Tree signs X Date Nov 1988	rosa Pine bears to these trees a State Regis or Agency	tration No. 852
respect to the new monument. The 10" Dougl S31°00'W, 54.1'. Attached Forest Service L repainted red bands and blazes on all of t x	as Fir bears S57°15' and Survey Monument he trees. Land Surveyor no Filed at	E, 75.6'. The 15" Ponde and Bearing Tree signs X Date Nov 1988	rosa Pine bears to these trees a State Regis or Agency	tration No. 852
respect to the new monument. The 10" Dougl S31°00'W, 54.1'. Attached Forest Service L repainted red bands and blazes on all of t x	as Fir bears S57°15' and Survey Monument he trees. Land Surveyor no Filed at	E, 75.6'. The 15" Ponde and Bearing Tree signs x Date Nov 1988 Pendleton, OR	rosa Pine bears to these trees a State Regis or Agency	tration No. 852
respect to the new monument. The 10" Dougl S31°00'W, 54.1'. Attached Forest Service L repainted red bands and blazes on all of t x	as Fir bears S57°15' and Survey Monument he trees. Land Surveyor no Filed at	E, 75.6'. The 15" Ponde and Bearing Tree signs x Date Nov 1988 Pendleton, OR	rosa Pine bears to these trees a State Regis or Agency	tration No. 852
respect to the new monument. The 10" Dougl S31°00'W, 54.1'. Attached Forest Service L repainted red bands and blazes on all of t x	as Fir bears S57°15' and Survey Monument he trees. Land Surveyor no Filed at	E, 75.6'. The 15" Ponde and Bearing Tree signs X Date Nov 1988 Pendleton, OR	rosa Pine bears to these trees a State Regis or Agency Date De	tration No. 852 c 1988 n.19 8 9

USDA-FOREST SERVICE	
Index File No. A-13	CORNER REGORD (SEARCH) Tract or Cor. (Ref. FSM 7151.4) Survey No. No.
T T65 R. R30E	R.D. UKIAH County UMATILLA
Merid. WILLAMETTE .	N.F. UMATILLA State OR
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
	FD. BASALT STONE 15"X8"X7" MKD CC + with notches
755 R30E	SET IN HO OF STONE
4 3	
N 4 3	2
c'c ·	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
T65R30E	
(60)	
PHOTO IDENTIFICATION DATA	1
Photo No.	
Filed At.	
Object ident	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Ident. By	
Signature 7	COR IS BZ FT NORTH OF E-W. FBNCELINE
PLANE COORDINATE POSITION DATA	
State Zone	
×	
Y	
Estab, By	
Agency 8	the state of the s
Signature Sagett	Title Division Headquarters Date 7100-52-(3/68) LAND Surveyor 9-30-76

1 1

			PO 902-67
	CORNER RECORD (PERPETUA		JO 902-67
	ONUMENT SET, OR WORK DONE TO PRESERVE EXISTING M	ONUMENT	
SET 21/2" X 30" 1 ROX	PIPE W/ BRASS CAPMKD.	T 55 R 30 E	
	. ,	S 3 3_	
		54 53	
	•	TES CC RZOE	
• .		1976 OPL5 5 9R	•
ACCESSORIES : DESCRIBE NE	W BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DO		<u></u>
NEW BIS			
A 10" FIR BRS. 56	I'E 744 FT. HKD TGSR30E S3CC B	7.	
A 15"FIR BRS 53	1°4 523 FT. HKD T65830E 54 CC B	7.	
	7		
			16
		State Begintration No.	
Work Done By. K. D. Bage	the Cand Surveyor Dote 9-30-76	or Agency OPLS 398	
Certified Cor. Record Prepared			1
	REMARKS		
			,
		/	t_{\perp}
			r
		•	• •

Tract or Surv. No.

Index File No. A-13 T.

R,

M.

Cor.