History of original corner establishment:

Unsurveyed - subdivided section

| DIA | AGRAM | | |
|-----|-------|----|------|
| т. | 55., | R. | 30E. |
| 4 | 5.3 | | |
| т. | 6S., | R. | 30E. |

No record of subsequent remonumentation found in County Record.

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set $2\frac{1}{2}$ " x 30" iron pipe 26" in ground with brass cap marked as shown: From which I scribed Bearing Trees.

A 11" fir bears S. 85° 34' E 33.6 ft. mkd. $\frac{1}{4}$ S.3 BT. A 11" fir bears S. 29°34' W. 18.3 ft. mkd. $\frac{1}{4}$ S.3 BT.

Nailed a brass washer mkd. PLS 933 to the BT blaze of both trees. Set steel fence post 4 ft. East of corner. Corner is 3 ft. South of E-W fence line. Used compass with 20° East variation and steel tape, measuring to the center of BFs.

PROFESSIONAL
LAND SURVEYOR

David A Kla

OREGON
DAVID H. KRUMBEN
933

| Office of County Surveyor County of Umat | illa |
|---|------------------------------|
| State ofOregon, I hereby certify that the within instrume | ent was filed in this office |
| for record on theday of | |
| (COUNTY OFFICIAL) by | |
| (COUNTY OFFICIAL) (D | EPUTY) |
| | |

A-15

Form R6-7100-57 (9/71)

☆ GPO---798-276

M-64