```
USDA-FOREST SERVICE
Index
                                              CORNER RECORD (SEARCH)
                                                                         Tract or
                                                                                           Cor.
File No. A-18
                                             Ref. FSM 7151.4
                                                                         Survey No.
                                                                                           No.
TES
                  R30E
                                    R.D.
                                             North Fork John Day
                                                                         County
                                                                                 Umatilla
Merid.
         Willamette
                                    N.F.
                                             Umatilla
                                                                         State
                                                                                 Oregon
Corner Diagram
                                    1 Describe corner monument found
                    W1/16
                                    1 Steel page extending 22" above the ground with a 2 1/2" brass cap stamped as
                                    I shown in the diagram, in a mound of stone.
                    00/52
                    1977
                   PLS 933
Photo Identification Data
                                    l Describe bearing trees or other official accessories found
Photo No.
                                    1 A 18" White Fir bears $35°56'W, 90.6' with healed scribe.
filed at
                                    1 A 11" White Fir bears $59°14'E, 13.4' with healed scribe.
Object Ident.
Ident. by
                  Signature
Plane Coordinate Position Data
                                    l Describe corner location relative to near-by features, also how to reach corner
State
                  Zone
                                    l From the junction of roads 5312 and 5320, follow 5320 east 1.6 miles to road
                                    1 5320110. Then follow road 5320110 east 0.6 miles to road 5320130. Follow road
                                    l read 5320130 south 0.4 miles to an east-west fence. Follow the fence west
Estab. by
                                      approximately 500' to the corner. -
                  Agency
        Signature
                           Title
                                             Division
                                                               Headquarters
                                                                                                     7100.52
                                                                                          Date
  David i. Haddock
                           Land Surveyor
                                                               Pendleton, OR
                                                                                          June 1988
```

	CORNER RECORD (PE				
X		χ			
Monument:Describe new monument set, or wo	rk done to preserve e	xisting	monument		
TRUE $CORA$ Set stee! guard post 5' west of the $\frac{1}{1000}$		st Servi	ce Land Survey A	lonument and Pronerty B	oundary
signs.			· ·	ichamana ana trabatal a	
х		Y.			
xAccessories:Describe new BT's witness obj	ects etc. established	or work	done to presery	ve existing evidence	
•		•	•		
Repainted bands and blazes on trees Red. (Attached Forest Servi	e Land	Survev Monument	sions to trees.	
	·				
X		x			
				State Registration	No.
Work done by David L. Haddock Title	Land Surveyor	Date	Nov 1988	or Agency	85
Certified cor. record prepared? yes	no x Filed at			Date	
x		x			
	REMARKŞ				
X		х			
x Index File No. A-18 T.65. R.30E.	M. Willamette	Tract o	r Survey No	Cor.	

USDA-FOREST SERVICE	t ·	•	
Index File No. <u>A - 18</u> T <u>6S</u> R 30E.	CORNER RECORD (SEARCH (Ref. FSM 7151.4)	Survey No	Gor
11/2 2 7 4 4	R.D. <u>Ukiah</u> County_	Umatilla	
Merid. Willamette .	N.FUmatilla State	Oregon	
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND		
T. 5S., R. 30E. W. 1/16	None Set brass cap		·
N CC S.2			
T. 6S., R. 30E.	DESCRIBE BEARING TREES OR OTHER OF	FICIAL ACCESSORIES FO	UND
	None		
•		•	
	•		•
PHOTO IDENTIFICATION DATA	•		
Photo No.			
Filed At.		•	•
Object Ident	DESCRIBE CORNER LOCATION RELATIVE 1	O NEAR-RY SEATURES A	LOO HOW TO BEACH CONTRACT
Ident. By	and the second s	O WEAK-DI FEATURES, A	LSO HOW TO REACH CORNER
Signature	· From the intersection		
PLANE COORDINATE POSITION DATA	From the intersection	or U.S. Forest	Roads 419N and 537N.
StateZone	as was by court to lelice	2.1 miles, then v	valk along fence East
X	40 chns. to corner.	•	
\$,	•	•
Falah Bu	i i		• •
Estab. By			•
Signature	Title Division Her	dguarters	4
Dwid HX Di		A N. L.	7100-52 (3/68)
	OPGS 8	7-3 - /-	-77

.

CORNER RECORD (PERPETUATION) MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT Set 2½" x 30" iron pipe with brass cap.		T. 6S., R. 30E. W. 1/16			
Pipe is 8" in ground. Mound of stones to cap	•		cc	5.2	
Stamped:	•			1977 PLS 933	
Set a steel fence post Painted red band aroun		w/sign.			
	· ·			·	10
Work Done By T. Hamby	Title Party Chief	Date 6/23/77 State Regis	tration No.		10
Work Done By T. Hamby Certified Cor Record Prepared ?	Yes X No Filed At:	Date <u>6/23///</u> or Agency _	tration No.		
		Date <u>6/23///</u> or Agency _			

Index File No.

Τ.

R.

M.,

Tract or Surv. No.

Cor.

13