USDA-FOREST SERVICE	¥-		
Index File No. A-2		RD (SEARCH) Tract or SM 7.151.4) Survey No	No. 1/16 Cor
T 6S R. 30E.		County <u>Umatilla</u>	
Merid. Willamette	N.F. <u>Umatilla</u>	State <u>Oregon</u>	
CORNER DIAGRAM	DESCRIBE CORNER MONU None	JMENT FOUND	
W/16 N 56			2
	DESCRIBE BEARING TREE: None	S OR OTHER OFFICIAL ACCESSORIES FOR	JND
PHOTO IDENTIFICATION DATA	4		
Photo No.			
Filed At.			
Object Ident	DESCRIBE CORNER LOCAT	ION RELATIVE TO NEAR-BY FEATURES, A	LSO HOW TO REACH CORNER
Ident. By Signature PLANE COORDINATE POSITION DATA	Corner is approx and visible from	imately 10' South of Road a	long Std. Parallel
State Zone			
XY	,		
Estob. By Agency 8		50-46 - 15-15 - 15-2 34.6 45 - 15-15	9/79 4
Signature	Title Divis	ion Headquarters D	oté 7100-52 (3/68)

T.6S

Index File No. A-2