History of original corner establishment:

Unsurveyed - subdivided section

T. 6S., R. 30E.
N.W. 1/16 S.2

No record of subsequent remonumentation found in County Record.

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set $2\frac{1}{2}$ " x 30" iron 14" in ground with brass cap marked as shown. From which I scribed Bearing Trees:

A 11" pine bears N. 85043' E. 21.3 ft. mkd. N.W. 1/16 S.2 BT. A 13" fir bears N. 65057' W. 41.6 ft. mkd. N.W. 1/16 S.2 BT.

Nailed a brass washer mkd. PLS 933 to the BT blaze on both trees. Set steel fence post 3 ft. North of corner. Raised mound of stone 3 ft. base within 5" of top of pipe. Used transit and steel tape, measuring to the center of BTs.

AEGISTERED
PROFESSIONAL
LAND SURVEYOR

ONEGON
OREGON
DAVID H. KRUMBEIN
933

N.W. 1/16 S.2

B-18

Form R6-7100-57 (9/71)

☆ GPO-798-276