## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established in 1881

by Frank W. Campbell, under contract 380

39.90 set a basalt stone  $16 \times 10 \times 5$  in mound of stone for  $\frac{1}{6}$  sec. cor.

A pine 6 in. diam. brs. N. 14 lks. dist.

DIA	GRAM		
т.	65.,	R.	30E.
		į.	
	S	.3	
	S	.10	_

No record of subsequent remonumentation found in County Records.

Description of corner evidence found:

Found a 17" pine with  $\frac{1}{2}$  on Blaze, bears N. 26°53% W. 35.10 ft. from brass cap set by Krumbein Engineering. The blaze has been cut out with chain saw.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a  $2\frac{1}{2}$ " x 30" iron pipe 18" in ground with brass cap marked as shown: From which I scribed New Bearing Trees.

A 12" pine bears S. 47°04" E. 60.5 ftc. mkds. 105310 BT. A 18" pine bears N. 45°27' W. 81 ftc. mkds. 1 5573 BT.

I nailed a brass washer mkd. PLS 933 to BT blaze on both trees. Set a steel fence post 5 ft. East of Corner. Raised mound of stone and earth with a 3 ft. base to within 2" of top of cap. Corner is 75 ft. North of old road.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
OREGON
JULY 17, 1970
DAVID H. KRUMBEIN
933

T. 6S., R. 30E.

1 S.3 S.10

1977
PLS 933

Office of County Surveyor County of Umatilla

State of Oregon I hereby certify that the within instrument was filed in this office for record on the I day of 19.

(COUNTY OFFICIAL) by (DEPUTY)

F-15

Form R6-7100-57 (9/71)

☆ GPO-798-276