History of original corner establishment: Corner established in 1881 by Frank W. Campbell, under Contract No. 380

Surveyor General Record States:

Set a basalt stone 10x8x8 in a md. of stone for 1/4 sec.

Pine 24 in. in diam. brs. S 18° E. 60 lks. dist.

DIAGRAM	
T6S.R30E.	
S1 S12	

No record of subsequent remonumentation found in County Records. Description of corner evidence found:

I did not find the original  $\frac{1}{3}$  corner stone. I establish this corner at record bearing and distance from the original bearing tree. From the corner point:

A 24" pine stump bears S.  $18^{\circ}$  E. 39.6 ft. mkd. BT at the base the scribing blaze axe marks are visible at the top of the stump.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the corner point: Set a  $2\frac{1}{2}$ "x30" galvanized iron pipe 20" in the ground with brass cap marked as shown. From which I scribe NEW BEARING TREES:

A 12" pine bears N. 49° E. 55.5 ft. mkd. T6S R30E  $\frac{1}{4}$  S1 BT. A 9" pine bears S. 34° E. 25.5 ft. mkd. T6S R30E  $\frac{1}{4}$  S12 BT.

I nailed a brass washed marked "OPLS 598" to BT blaze of both trees. Set a steel fence post 5 ft. west of corner. Raised a mound of stone 3 ft. base to top of pipe. Corner is 10 ft. SE of old logging road. Used compass with 20° East variation and steel tape measuring to center of new BTs.

REGISTERED PROFESSIONAL LAND SURVEYOR		
OREGON ROBERT D. BAGETT		765 R30E 3 S12
Sept. 30,1976 Office of	Countries Umatilla	1976 OPLS 598
	y that the within instrument was filed in this office	* <sub>2</sub> 3
(COUNTY OFFICIAL)	by(DEPUTY)	E-L

Form R6-7100-57 (9/71)

☆ GPO-798-276

S-60-M