CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History	of	orig	inal	corner	establi	shment:
---------	----	------	------	--------	---------	---------

Frank W. Campbell under Contract No. 380 dated March 19,

Set Pine Post from which

Pine, 30" Dia., BRS. S72°E., 22 Lks. Dist. Pine, 30" Dia., BRS. S60°W., 63 Lks. Dist. Pine, 30" Dia., BRS. N68°E., 72 Lks. Dist. Pine, 18" Dia., BRS. N66°W., 69 Lks. Dist.

DIAGRAM T6S R30E S6 | S5 S7 | S8

Description of corner evidence found:

Found no original evidence.

Description of monument and accessories I established to perpetuate the original location of this corner

Set 32" X 2" flanged iron pipe with brass cap marked: From which

Ponderosa Pine, 7" Dia., BRS. N46°E., 18.5 Ft. Dist. Marked: T6S R30E S5 BT

Douglas Fir, 10" Dia., BRS. S37°E., 26.7 Ft. Dist. Marked: T6S R30E S8 BT

Douglas Fir, 14" Dia., BRS. $\rm S17^{O}W_{\odot}$, 33.7 Ft. Dist. Marked: T6S R30E S7 BT

Douglas Fir, 18" Dia., BRS. N48°W., 48.4 Ft. Dist. Marked: T6S R30E S6 BT

6' iron fence post with "Survey Monument" sign within 5' of corner.

All B.T. have BT tag and painted red stripe. New BTs have brass washer stamped: PLS 346; nailed to lower blaze.

Office of County Surveyor	County of Umatilla
State of Oregon , I hereby certify th	
for record on the day of	
(COUNTY OFFICIAL)	(DEPUTY)

RECEIVED BY

Form R6-7100-57 (9/71) Umatilla County Surveyor

Date_10-17-79

Rec'd By my

WAYNE O. HARRIS 346

PROFESSIONAL LAND SURVEYOR

T6S R30E S6 |S5 S7 |S8

1979

PLS 346

⊕ GPO 796-333