

USDA-FOREST SERVICE

Index File No. J-3

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or Survey No. _____ No. J-3


T 6S R. 31E

R.D. Ukiah County Umatilla

Merid. Will.

N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND 2

Found 1 dead and badly rotten pine snag bearing S16°E 96 links from corner. This will not last too long. Scribing is gooding ¼ can be seen easily. Painted a 6" red band around it and also scribing around it and also scribing faces; put a bearing tree tag on scribed side and an attention sign on back, put up a steel post with the usual sign attached. It is about 3' north of Cor. location. 3

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature 7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency 8

Signature MLC

Title For, Tech Division USFS Headquarters Ukiah Date 4/20/78 7100-52-(3, 68) 4