Subdivisions if T, 1 N., R. 33 E. Surveyed by Z.F. Moody under contract No. 145 Dated April 23, 1871. 0.0

		T	
	Chains	North between secs. 34 and 35.  Var. 19° 30'East.	
	40.00	The state of the s	
		Set stone, 18x14x8, for \( \frac{1}{4} \) sec. corner.	
	80.00	Set stone, 20x12x9, for corner to sections 26, 27,34 and 35.	<del> </del> 750
		Land, steep.	
		Soil, 2nd rate, and stony.	
		North between secs. 26 and 27.	
		Var. 19° East.	
	31.50	Top of hill, on Western slope of mountain.	<del> </del> 350
88	40.00	Set stone, 20x20x10, for ½ S. cor.	[3]
	80.00	Set stone, 16x15x8, for corner to secs. 22, 23, 26 and 27.	-550
		Land, steep.	
		Soil, poor, 2nd rate, very stony.	
		4 1 2 1 2	l r
		North between secs. 22 and 23.	-
		Var. 19°East.	-
#	27.50	Foot of hill.	-450
	40.00	Set stone, 30x24x18, for \( \frac{1}{4} \) sec. cor.	
	64.00	Top of hill.	<del>+</del> 650
	80.00	Set stone, 24x18x14, for corner to secs. 14, 15, 22 and	-350
		23.	
		Land, steep.	
		Soil, poor, 2nd rate, very stony.	
		#2	
		North between secs. 14 and 15.	
0.000		Var. 20°East.	_
	19.00	Canyon, course W.	-450
	40.00	Set stone, $14x12x8$ , for $\frac{1}{4}$ sec. corner.	
	54.30	Top of hill.	†400
	80.00	Set stone, 18x14x8, for corner to secs. 10, 11, 14 and	-300
		15.	
		Land, hilly.	
	-	Soil, 2nd rate.	
		Grass, good.	