## T. 1 N., R. 35 East

1	Chains		
25		Water in holes.	
	58.50	Top of ridge.	<del>†</del> 5
	67.20	A Branch 15 lks. wide runs North.	-4
	80.00	Set post corner to Secs. 35 & 36, from which	†4
200	37, 12	A Tamarack, 12 ins. in diam. bears S.25°W 18 lks. dist	
		A Pine 12 " " " N.50°W. 36 lks. "	
X (B)		A Tamarack 12 " " " N60°E., 7 " "	
		Variation 20°45'East.	
		Surface of this mile is badly broken, but little room for	
		soil. Timber as before.	
		Thence East on South boundary of Sec. 36.	
		Var. 20°45' East.	
	15.00	Commence to descend.	
	15.00	Bottom of ravine. Dry branch, 10 lks. wide, runs North.	-6
	32.50	According to the second	
	40.00	Set qr. sec. post on the side of ridge and from which	†4
199		A Pine 36 ins. in dia. bears S70°E., 48 lks. dist.	
25	1044 CENTY	" " 14 " " " " S35 E. 112 lks. dist.	
	47.00	Top of table.	+2
1 3	80.00	Set post corner to secs. 31 & 36, Township 1, North,	
		Ranges 35 & 36 East, from which	
		A Spruce, 8 ins. in diam. bears N60°E 31 lks. dist.	
	e <b>r</b> a	A Pine 14 " " " N15°W 37 " "	3
	× ± <sub>0</sub>	" " 12 " " " S50°W 32 " " Var.20°30' E.	
-		Surface of last half mile slightly uneven. Soil and	
		timber as before.  August 9th, 1863.	
		Field Notes of the Survey of the East boundary of T. 1, N., R. 35 E., by Z. F. Moody, under his contract No. 145, dated Apr. 23, 1871.	
		From the South East corner of Township 1 North, Range 35	
55.00	*5.	East, I run	
		North on East boundary of Sec. 36.	
		Mandelineton Higher Schurzungen is leits their life	