| | Chains | . Subdivisional lines, T.1 N., R. 35 E. | ī |
|--------|--------------|--|----|
| • * * | Onains | Com l and annual marked lo on N Com Community | |
| 4 | | for \(\frac{1}{4} \) sec. corner, marked \(\frac{1}{4} \) on N face, from which | |
| | - 34 | A Fir, 4 ins. diam.bears N20°W.20 lks. dist., marked | |
| | | 1 S.B.T. | |
| | E . | A Spruce, 8 ins. diam. bears S87°W.50 lks. dist., | |
| | (25) | marked 1/4S. B. T. | |
| | 42.25 | Creek, 2 lks, runs N.W. | -3 |
| | 60.00 | Summit Hill N.W. | +5 |
| · 1 | 77.50 | Gulch N.W. | -3 |
| * | 80.00 | Set basalt stone 12x12x6 ins. in mound of stone for | |
| | 81.5 | corner to secs. 1,2,11 & 12, marked with 5 notches | |
| 229 | | on S and 1 notch on East edges. This corner stone | |
| ** | | sits on top of ground as digging is impracticable, | |
| | | owing to the surface being rocky. | |
| - 10 - | | Land, mountainous. 80.00 chs. | |
| 50 50 | | Soil, 2nd & 3rd rates. Grass, good. | |
| | | No timber. | |
| | | | |
| | - n- | South on true line between secs. 11 & 12. | |
| | | Var. 27°21' East. | |
| | 25.50 | Canon and brook, 5 lks, runs W. | -1 |
| 5 | | Ascend. | 3 |
| | 40.00 | Set basalt stone 12 x 12 x 8 ins., 8 ins. in the ground | |
| | 1000 | for \(\frac{1}{4}\) Sec. corner, marked \(\frac{1}{4}\) on W. face and raised | |
| 9 6 | | 20 10 1000 The State Control of the State Control o | |
| = | 68.06 | mound of stone over it. Pits impracticable. | |
| | 00.00 | Intersect U.R. bdy. 17.87 chs. S.20°W of 1/2 M. cor. on | |
| | | 46th Mile and set basalt stone 12 x 12 x 10 ins., 8 ins. | |
| | | in the ground for closing corner to secs. 11 & 12, marked | |
| | | U.R.C.C. on N. face and raised mound of stone over it. | |
| | | Pits impracticable. | |
| | | Land, rough and mountainous 68.06 chs. | |
| * | | Soil, 3rd rate. Grass, good. | |
| . 1 | 1 3 m a c 10 | Timber on S. side of canon, Pine and fir. | |
| | | 8 | |
| | | | |