Subdivisional lines, T. 1 N., R. 35 E.

	Chains	Subdivisional lines, T. 1 N., R. 35 E.	1
	Onams	North bet. secs. 9 & 10.	G
	*	Var. 174° East.	
1.0	22.00	Gulch W.	-200
	40.00	Summit sharp ridge and set basalt stone 16x16x8 ins.,12 ins	193
-1	40.00	in the ground for \$ S. corner, marked \$ S on W.face;	1000
	227 10	DANCE CONTROL OF THE THE TANK THE TANK AND THE TANK THE T	
		raised mound of stone over it. Pits impracticable.	350
(mr)	52.50	Gulch, W.	-150
(Per	62.00	Proceedings and design as a second of the se	1 200
	77.25	Gulch W.	-200
	80.00	Set stone 14 x 12 x 12 ins., 8 ins. in the ground for	
15		cor. to secs. 3, 4, 9 & 10, marked with 5 notches on S.	
	1 11	and 3 notches on East edges; raised mound of stone over	
		it. Pits impracticable.	
		Land, rough and mountainous 80.00 chs.	
	9	Soil, 3rd rate and very rocky. Grass, good. No timber.	
)		22-5 14 15 2 2 4 4	
14 120		East on random bet. secs. 3 & 10.	
	-	Var. 19° East.	
1	40.00	Set temporary 1/4 S. cor. and at	
N 72	80.25	Intersect E. bdy. 42 lks. N. of cor. to Secs. 2, 3, 10 &	
t		11,	
		Thence	
		N.89° 42' West on true line.	
		Var. 19-3/4° East:	
8	11.50	Summit N.	 150
UR.	40.12	Set stone 20 x 14 x 12 ins., 14 ins. in the ground for 1/4	
		sec. cor., marked 1 on N. face, from which	
		A Tamarack 10 ins. in diam. bears S.20°W.68 lks.dist.,	
) .		No other tree within limits; raised mound of stone over	
		it.	
	62.50	Summit N.	+300
000	80.25	Cor. to secs. 3, 4, 9 & 10.	
1		Land, rough and mountainous 80.25 chs.	
765		Soil, 1st rate. Grass, good. Scattering timber, pine and	
		fir, and some underbrush, same.	
		June 22, 1887.	
		ound 22, 1007.	

KILHAM 1962