

Resurvey of South Bdy. of T. 2 N., R. 37 E.

Chains	
	<p>Thence I run S.89°55'W. on old township line between secs. 1 and 36. Ascend E. slope of divide, through heavy timber and dense undergrowth.</p>
40.24	<p>Intersect old $\frac{1}{4}$ sec. cor., which is a post badly decayed. Marks obliterated and witness as described by the surveyor general. I destroy old post and set an iron stone, 24x15x10 ins., 18 ins. in the ground, for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ on N. face, from which the witness trees bear as stated by the surveyor general.</p>
	<p>Thence I run</p>
	<p>N.88°45'W.</p>
50.25	<p>Summit of divide between Grande Ronde and Umatilla Basins, 300 ft. Tp. cor. bears N.20°W., S.20°E.; descend.</p>
62.00	<p>Over swampy ground, bears N. and S.</p>
63.50	<p>Leave swampy ground and ascend over rolling land on N. slope of ridge.</p>
72.00	<p>Top of ridge, point 150 ft. high, bears N. and S. Descend.</p>
79.00	<p>Enter scattering timber, bears N. and S. 10°E.</p>
80.24	<p>Intersect the cor. of secs. 1, 2, 35 and 36, which is a post entirely decayed in mound of stone, and witnessed as described by the surveyor general. I set a basalt stone, 15x10x8 ins., 10 ins. in the ground, at the same point for cor. of secs. 1, 2, 35 and 36, marked with 1 notch on E. and 5 notches on W. edges, from which the witness trees bears as stated by the surveyor general.</p> <p>Land, mountainous and rolling. Soil, stony and loam, 3rd, 4th and 1st rate. Timber, fir, pine, tamarack, spruce, larch and yew. Undergrowth, mountain laurel, huckleberry, vine maple and small firs.</p> <p>Mountainous or heavily timbered land. 80.24 chs.</p>
	<p>N.89°20'W. on old township line between secs. 2 and 35. Descend through heavy timber and dense undergrowth.</p>