

East Bdy., T.1 S., R.31 E., W.M.
 As surveyed by David P. Thompson, Deputy Surveyor.
 Under Contract No. 106, dated Aug. 16, 1864.

Chains		Feet
	From the Cor. to Tps. 1 & 2 S., Rs. 31 & 32 E., I run N. on E. Bdy. of Sec. 36 Var. 20° 30' E. Descend hill	
40.00	Set stone, 24 x 8 x 8 ins. for $\frac{1}{4}$ Sec. Cor..	
80.00	Set post for Cor. to Secs. 30, 31, 25 & 36, in mound of earth with charred stake, pits, trench, etc. as per instructions.	
	Land; gently rolling.	450
	Soil; good 2nd rate. Oct. 6th, 1864.	
	N. on E. Bdy. of Sec. 25. Var. 19° 30' E. Descend hill.	
40.00	Set post for $\frac{1}{4}$ Sec. Cor., in mound of earth with charred stake, pits, trench, etc. as per instructions.	
40.10	Road brs. N.E. & S.W.	
40.60	Enter field, brs. N.E. & S.W.	
46.60	Birch Creek, 6 lks. wide, foot of hill, runs N.E.	150
60.00	Leave field, brs. N.E. & S.W. Ascend hill	
80.00	Set stone, 24 x 12 x 8 ins. for Cor. to Secs. 24, 25, 19 and 30.	150
	Land; gently rolling. Soil; 1st rate.	
	N. on E. Bdy. of Sec. 24. Var. 23° E.	
10.00	Top of hill, descend hill.	100
40.00	Set post for $\frac{1}{4}$ Sec. Cor. in mound of earth, with pits, trench, etc., as per instructions.	
50.00	Deep ravine, brs. N.E.- Ascend hill	250
80.00	Set post for Cor. to Secs. 18, 19, 13 & 24, in mound of earth with pits, trench, etc., as per instructions	300