East Bdy. of T. 1 S., R. 34 E., W.M.
As surveyed by James P. Currin and James E. Noland,
U.S. Deputy Surveyors,
Under their Special Contract
Dated may 4th. 1887.

_			Dated may 4th, 1887.
		Chains	E. on random line on S. Bdy. of T. 1 S., R.34 E. Fee Var. 22 ° E.
	-		I set temp. half mile and mile Cors. at each 40 and 80 chs
}			and find the Tp. line to be 6 miles, 2 chs. and 70 lks.
j	11.000		and the falling to be 4.88 chs. S. of Cor. to Tps. 1
			and 2 S., Rs. 34 & 35 E. Which is a post 4 ft. long,
			4 ins. sq., 2 ft. in ground one a steep hillside fact-
	546		ing East, 300 ft. above bottom of canyon, 400 ft. be-
			low summit, marked T.1S., S.31 on N.E.
		27.	R.35E.,S.6 on S.E.
			T.2S.,S.1 on S.W.
			R.34 E.,S.36 on N.W. with 6 notches
			on N., S., E., and W. edges, from which,
			The second secon
			A pine, 8 ins. diam., brs. N. 26° E., 112 lks. dist.
Y.:			marked T.1 S., R.35 E., S.31, B.T.
i I	**		With mound of stone around post.
ři.			June 24, 1887.
			Thence I run
			S.89° 25' W. on true line, along S. Bdy. of Sec. 36.
	2	Sm 66	Var. 20° 30' E.
		27.00	Summit of mountain
		40.00	Set a basalt stone, 10 x 8 x 7 ins., 7 ins. in ground for
	-		\$ Sec. Cor., marked & on N. face. Raised mound of stone
			alongside. Pits impracticable.
		55.00	Canyon, course N.
		77.00	Summit of mountain
		80.00	Set a basalt stone, 12 x 9 x 7 ins., 8 ins. in ground for
			Cor. to Secs. 1, 2, 35 & 36, marked 1 notch on the E.
			and 5 on W. edges. Raised mound of stone alongside. Pits
	: 1		impracticable.
	1856		Land; mountainous, 80.00 chs.
	-		Soil; 4th rate, scattering pine timber in canyons.
	1550 E		
		أأورمه	S.89° 25' W. on S. Bdy. of Sec. 35.
			Var. 20° 30' E.
		31.50	Dry gulch, course S.W.