South Boundary of T. 3 N., R. 35 E.

Chains	Land, broken and stony.	
	Soil, good, 2nd rate.	
	Timber, consists of balm, pine &c.	
	Some undergrowth.	1
. 8	Some didergrowth.	
	East on South boundary of sec. 33.	
	Var. 19°30'E.	
40.00	Set stone, 17x14x9, for 1/4 sec. cor. on hill facing toward	
g %c	South.	
80.00	Set stone, 18x10x10, for cor. to secs. 33, 34, 3 and 4.	
3	Land, broken and stony.	
	Soil, 2nd rate.	
		L
	East on South boundary of section 34.	
	Var. 20°E.	
23.50	Enter timber in river bottom.	1
30.50	Umatilla River, 250 lks. wide, flows South West.	
40.00	Set post and made stone mound for $\frac{1}{4}$ sec. cor.	
70.00	Leave timber.	
80.00	Set post and made stone mound for cor. to secs. 34, 35,	
7.	2 and 3.	
ļ	3	
	East on South boundary of section 35.	
	Var. 20°30'E.	
40.00	Set post and made stone mound for $\frac{1}{4}$ sec. cor.	
80.00	Set stone, 17x14x12, for cor. to secs. 35, 36, 1 and 2.	
	Land, hilly.	
	Soil, 2nd rate.	()+-
	East on South boundary of sec. 36.	-
	Var. 21°E.	
15.00	Brook, 12 lks., flows North.	-100
40.00	Set post and made mound of earth for $\frac{1}{4}$ sec. corner.	
80.00	Set post and made mound of earth for corner to Tps. 2 and	
	3 North, Ranges 35 and 36 East of the Willamette	
	Meridian.	