## South Boundary of T. 3 N., R. 35 E.

0 8	Chains	for cor. to secs. 33 and 34, marked 3 notches on E. and	r
		W. edges. Raised a mound of stone over it. Pits impracticable.	<b>†15</b> 0
		Land, mountainous. 16.40 chs.	
		Soil, gravelly in bottom, 4th rate.	
		Heavy brush; pine and balm timber in bottom. 63.60 chs.	
		South 89°50'W. on S. bdy. sec. 33.	-
		Var. 18°E.	
	11.60	Head of gulch, course S.	-60
	40.00	Set a basalt stone, 14x10x6 ins., 9 ins. in the ground,	420
		for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on N. face. Raised mound of	
		stone over it. Pits impracticable.	
	61.40	Summit of ridge.	+10
	68.40	Spring branch, 2 lks. wide, course S.	-10
	80.00	Set a basalt stone, 12x10x8 ins., 8 ins. in the ground,	
× 1		for cor. to secs. 32 and 33 marked 4 notches on E. and	
	a 1	2 notches on W. edges. Dug pits, 18x18x12 ins., N. E.	
	= 1	and W. of cor., $5\frac{1}{2}$ ft. dist., raised mound of earth 2	
		ft. high, $4\frac{1}{8}$ ft. base alongside.	-20
		Land, mountainous. 80.00 chs.	
		Soil, rocky, 4th rate.	
		Poor grass. No timber.	
		South 89°50'W. on S. bdy. sec. 32.	
	106	Var. 22°15'E.	
	3.40	Wagon road, course N.W. and S.E.	
		Enter bottom.	
	12.50	Umatilla river, 120 lks. wide, course N.80°W.	
	19.50	Umatilla River, 120 lks. wide, course S.70°W.	
	40.00	A pine, 7 ins. diam., which I marked & S on N. face, for	
		1 sec. cor. Raised mound of stone alongside. Pits	
	19 50	impracticable.	
	48.50	Umatilla River, 75 lks. wide, course N.W.	
	68,00	Umatilla River, 50 lks. wide, course S.W.	
1	78.50	Umatilla River, 80 lks. wide, course N.W.	

KILHAM 1867