a	T. 3 N., R. 36 E. (N.bdy. T.2 N., R. 36.)	7
Chai	200	05
80.0		-25
	side facing the North, from which	
	A fir 10 ins. in diam. bears N.38° E. 27 lks.	1
100	" " 7 " " " N.62° W. 41 "	
	" 10 " " " S.43° W. 38 "	
	" " 12 " " " S.51° E. 25 "	
	This line passes over very rough, broken mountain ridges	
	the last 10-00 chs. passes through thick timber, small	
	growth fir, larch and pine.	
*		
	East on south boundary of section 34.	ĺ
-	Var. 20° 30' East.	
22.5	Creek, 10 lks. wide, course North.	-30
40.0	Set post corner for \(\frac{1}{4} \) section on steep hillside, facing	+30
	the West; drove charred stake, dug pits, and raised	
	mound as per instructions.	(
47.5		+150
80.0		-80
	point of rocks; deposited marked stone and raised stone	
w	mound, as per instructions.	
. 5.0	This line passes over broken mountain ridges. Timber on	9
	most of the northern slopes.	
14		
	East on south boundary of section 35.	
	Var. 19° East.	
5.7		- 75
40.0	E TO SECTION S	+ 350
40.0	A fir, 12 ins. in diam. bears S.70° East 14 lks.	1000
	No other tree near; dug pits and raised mound, as per	[
		1
	instructions.	1500
60.0	Summit of ridge, course S.W. Var. 21° East.	† 500
80.0	Set basalt stone 7 x 9 x 24 on steep side hill facing the	- 50
	south.	
	This line passes over very broken, mountain ridges, quite	