 Chains	T. 2 N., R. 37 E.(W. bdy. T. 2, N.R., 36 E.)
	A tamarack, 4 ins. in diam. bears S.71° W.17 lks.dist.
	marked T.2, N.R. 36 E. S.36 B.T.
	A tamarack, 5 ins. in diam. bears N. 60° W.31 lks.
	dist., marked T 2 N R 36, E. S.25 B.T.
	A spruce 3 ins. in diam. bears N. 45° E. 4 lks.
	dist., marked T.2, R.37, E. S.30 B.T.
1 2	A fir, 2 ins. in diam. bears S. 66° E. 8 lks. dist.,
2	marked T.2, N.R. 37, S.31, B.T.
	Land, mountainous and broken.
45	Soil, rocky, 4th rate.
	Timber, fir, tamarack, spruce and pine.
	North bet. secs. 25 and 30.
	Var. 19°35' East.
	Descend through dense chaparral.
15.00	Ascend through chaparrel and occasional barren spots.
30.00	Summit of slightly rolling table land.
00.00	Slight descent.
40.00	Post 3 ft long, 3½ ins. square, 1 ft. in ground, marked
40.00	1 S on E & W faces and raised a mound of stone about
	base of post 30 inches at base and 15 inches high for
	2000 TO 1000 1000 1000 1000 1000 TO 10
	1 sec. cor., from which
	A fir, 12 ins. in diam. bears S.5° W. 145 lks. dist.,
	marked 4 S.B.
50.60	Brink of canyon 1000 ft. deep, course N. and for about
	3 miles ahead is a succession of rocky, precipitous
	mountain gorges, barren rocky slides, where chaining is
	impracticable so I discontinue the survey of this town-
	ship at the last \frac{1}{4} sec. corner.
	Land, mountainous and broken.
	Soil, very rocky, 4th rate.
	Timber, fir, pine and tamarack.
	Sept. 29, 1881.

. .