Subdivisions of T. 3 North, R. 33 East

C	hains	No timber.
		Short grass. Aug. 16th 1887
	6	Constant Description
1 1		General Description This township is mostly level, excepting parts along
		the Wild Horse creek and Umatilla river, which is
		rolling. The soil is first rate. No timber. Grass,
		short.
		Survey of the Sub-Subdivisional lines of Township 3 North, Range 33 East Willamette Meridian, in the state of Oregon, by James P. Currin and James E. Noland under their joint special contract.
		Commenced the survey of the Sub-Subdivisional lines of this Township on Oct. 26, 1887.
	(+)	East on random through S. 2 of Sec. 36, T. 3 North, R. 3
		East.
		Va. 20° East.
		Commencing at 1/16 sec. cor. 20 chains S. of 2 sec. cor.
*		bet. Secs. 35 and 36. Thence
		East, setting temporary cors. at 20.40 and 60 chains and at
	78.90	Intersect E. bdy. 60 lks. S. of 1/16 sec. cor. Thence S.89°34' W. on true line.
	19.72	Deposited charred stake 12 ins. in the ground for 1/16
		sec. cor., dug pits 18x18x12 ins. E. and W. of stake,
		5% ft. dist., raised mound earth 1% ft. high, drove
		stake 2 ft. long, 2 ins. square, 12 ins. in the
-		ground, marked 1/16 S on N. face.
	35.50	Wagon road bears N. and S.
	39.00	Wagon road bears NE. and SW.
	39.45	Deposited charred stake 12 ins. in the ground for 1/16
	74	sec. cor., dug pits 18x18x12 ins. E. and W. of stake,
		$5\frac{1}{2}$ ft. dist., raised mound of earth $1\frac{1}{2}$ ft. high, $3\frac{1}{2}$
30 3		ft. base over it, and in E. pit drove stake 2 ft. long
		2 ins. square, 12 ins. in the ground, marked 1/16 S