			11 197		22
e u	26-		2 2		20
Subdivisional	Lines of Townshi	p 3 North,	Range 36 E.	W. M.	

	Chains 19.00	Road, E. & W. to timber.	
	35.46	Set stone 16x12x7. for 2 sec. cor.	-50
		A pine, 40 in diam. brs. S. 18° E. 154 lks. dist.	
		A pine, 28 in diam. brs. S. 8° W. 247 lks. dist.	1
		Also a house bears S. 52° E. ) David Howdy	
	41.40	Same House bears N. 62° E. ) Shell's House.	
	68.00	Brook; #15tikscwide, course West.	-200
	75.46	The cor. to Sec. 4, 5, 8 and 9.	1200
		Land: Surface, hilly. Soil, 1st & 2nd rate. Timber,	1000
		mostly scattering. South of brook, good. Fir, pine	
200940		& tamarack. Most of this is good farming land.	=
		South between Sec. 8 and 9.	
		Va. 21°10' East.	
**	5.00	Z. W. Boatman's cabin brs. S. 48° W.	
-	15.00	Z. W. Boatman's cabin brs. N. 52.º W.	-
	28.11	To a point on Umatilla Indian reservation line, by mean-	
	1 1	ders 24.10 chs. East of 31st mile post. Set fir post	
		at point of intersection for corner to Sec. 8 and 9.	
		. A fir, 14 in diem. brs. N. 40° E. 48 lks. dist.	
		. A fir, 10 in diam. brs. N. 77° W. 46 lks. dist.	
		Land: Surface, hilly. Soil, 1st & 2nd rate. Scattering	
		timber, pine, temarack and fir. Good grass. This is	
	1 - A	good farming land. October 20th 1878.	
	- Ø		
		West on a true line between Sec. 5 and 8.	
		, Va. 21°10; East.	
	40.00	Set fir post on North hillside nearttop of hill for 2	
		sec. cor.	
		Tamarack, 8 in diam. brs. N. 4° E. 15 lks. dist.	1. (
		Tamarack, 10 in diam. brs. S. 2° W. 6 lks. dist.	
	68.50	Brook. 12 lks. wide, course SW. Also leave timber	+350
	80.00	Set stone 28x12x7 on South hillside for cor. to Sec. 5,	+150
		6, 7 and 8, from which a	
192		Pine, 28 in diam. brs. S. 11° E. 282 lks. dist.	
	1	Fir, 20 in diam. brs. S. 20° W. 390 lks. dist.	