William

9.90	Wagon road, E. and W.
9.47	To cor. to Secs. 16, 17, 20 and 21.
	Land, broken and mountainous. 79.47 chs.
	Soil, 3rd rate.
	Timber; pine and fir and underbrush.
	Good grass.
- 4	
-	North bet. Secs. 31 and 32.
	Va. 13° East.
0.00	Meacham Creek, N. 20° East.
9.00	Same " N. 20° W.
9.50	Same " N. 45° E.
10.00	Set post, 3 ft. long, 3 ins. square, 24 ins. in the ground
	for ½ sec. cor., marked ½ S on W. face, from which
	A fir, 36 ins. S. 70° E. dist. 25 lks., marked \(\frac{1}{4}\) S B T.
	A pine, 30 ins. in diem. bs. N. 85° W. dist. 20 lks.,
-	marked & S B T.
4.50	Meacham Creek, 30 lks. NW.
7.50	Same * 30 lks. NE.
1.50	Same " 30 lks. NW.
6.50	House in small inclosure.
0.00	Set post, 4 ft. long, 4 ins. square, 24 ins. in the ground
	for cor. to Secs. 29, 30, 31 and 32, marked T 3 N S 29
-	on NE., R 36 E S 32 on SE., S 31 on SW. and S 30 on NW
	faces, with 1 notch on S. and 5 notches on E. edges
-	from which
	A pine, 16 ins. diam. bears S. 25° W. 57 lks. dist.,
8	marked T 3 N R 36 E S 31 B T.
	A birch, 5 ins. diam. bears N. 15° W. 38 lks. dist.,
	marked T 3 N R 36 E S 30 B T.
1	No other trees in limits and raised mound of stone
23	over it.
	Land, mostly creek bottom.
	Soil, 2nd rate, gravelly.
	Dense brush, pine & Balm timber. 80.00 chs.