40.00 Set Fir post on level for \$\frac{1}{4}\$ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.	Chair	A Fir, 30 Ins. in diam., bears S. 64° W. 170 Lks.dist.
Good timber on North hillsides. Fir, Tamarack and Pine. Good grass on South hillsides.  April 19, 1879  North on the East Boundary of Section 12  Var. 18° 30' East  12.00 Enter timber, East & West  20.00 Enter " " "  30.00 Enter " " "  30.00 Fook, 3 Lks. wide, course West  A Fir, 7 ins. in diam. on S.W.hillside for \( \frac{1}{4} \) Sec. Corner  A Fir, 12 ins. in diam., bears S.70° E. 25 Lks.distant  " 6 " " " S.72° W. 8 " "  44.50 Prook, 25 Lks. wide, course S.W.  72.00 Open glade Set Basalt Stone 14 x 12 x 4 on S.E. face of mountain in mound of stone for Corner to Sec. 1, 12, 6 & 7.  A Pine, 10 ins. in diam., bears N.18° E. 51 Lks. dist.  " 18 " " S.70° E. 107" "  " Fir 14 " " " S.74° W. 160" "  No other trees Land; surface, mountainous. Soil, 3rd rate & worthless. Some good timber in places, but mostly scattering Tamarack Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  40.00 Set Fir post on level for \( \frac{1}{4} \) Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.		
Cood grass on South hillsides.  April 19, 1879  North on the East Boundary of Section 12  Var. 18° 30' East  12.00 Enter timber, East & West  20.00 Leave " " " "  36.00 Brook, 8 Lks. wide, course West  A Fir, 7 ins. in diam. on S.W.hillside for \$\frac{1}{2}\$ Sec. Corner  A Fir, 12 ins. in diam., bears S.70° E. 25 Lks.distant  " " 6 " " " S.72° W. 8 " "  44.50 Brook, 25 Lks. wide, course S.W.  72.00 Open glade  80.00 Set Basalt Stone 14 x 12 x 4 on S.E. face of mountain in mound of stone for Corner to Sec. 1, 12, 6 & 7.  A Pine, 10 ins. in diam., bears N.18° E. 51 Lks. dist.  " " 18 " " " S.74° W. 180" "  No other trees  Land; Surface, mountainous. Soil, 3rd rate & worthless.  Some good timber in places, but mostly scattering Tamarack Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  40.00 Set Fir post on level for \$\frac{1}{2}\$ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.		300
North on the East Boundary of Section 12  Var. 18° 30' East  12.00 Enter timber, East & West  20.00 Leave " " " "  36.00 Enter " " " "  36.00 Brook, 8 Lks. wide, course West  A Fir, 7 ins. in diam. on S.W.hillside for \$\frac{1}{2}\$ Sec. Corner  A Fir, 12 ins. in diam., bears S.70° E. 25 Lks.distant  " " 6 " " " \$ S.72° W. 8 " "  44.50 Brook, 25 Lks. wide, course S.W.  72.00 Open glade  80.00 Set Basalt Stone 14 x 12 x 4 on S.E. face of mountain in mound of stone for Corner to Sec. 1, 12, 6 & 7.  A Pine, 10 ins. in diam., bears N.18° E. 51 Lks. dist.  " " 18 " " " \$ S.70° E. 107" "  "Fir 14 " " " \$ S.74° W. 160 " "  No other trees  Land; surface, mountainous. Soil, 3rd rate & worthless.  Some good timber in places, but mostly scattering Tamarack Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  40.00 Set Fir post on level for \$\frac{1}{2}\$ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.		
North on the East Boundary of Section 12  Var. 18° 30' East  12.00 Enter timber, East & West  20.00 Leave " " " "  30.00 Enter " " " "  36.00 Brook, 8 Lks. wide, course West  40.00 A Fir, 7 ins. in diam. on S.W.hillside for \$\frac{1}{2}\$ Sec. Corner  A Fir, 12 ins. in diam., bears S.70° E. 25 Lks.distant  " " 6 " " " " S.72° W. 8 " "  44.50 Brook, 25 Lks. wide, course S.W.  72.00 Open glade Set Basalt Stone 14 x 12 x 4 on S.E. face of mountain in mound of stone for Corner to Sec. 1, 12, 6 & 7.  A Pine, 10 ins. in diam., bears N.18° E. 51 Lks. dist.  " " 18 " " " S.70° E. 107" "  " Fir 14 " " " S.74° W. 160" "  No other trees Land; surface, mountainous. Soil, 3rd rate & worthless. Some good timber in places, but mostly scattering Tamarack Fir and Fine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  40.00 Set Fir post on level for \$\frac{1}{2}\$ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.	4.5	Good grass on South hillsides.
Var. 18° 30' East  12.00 Enter timber, East & West  20.00 Leave " " " "  30.00 Enter " " " "  36.00 Brook, 8 Lks. wide, course West  40.00 A Fir, 7 ins. in diam. on S.W.hillside for \$\frac{1}{2}\$ Sec. Corner  A Fir, 12 ins. in diam., bears S.70° E. 25 Lks.distant  " " 6 " " " S.72° W. 8 " "  44.50 Brook, 25 Lks. wide, course S.W.  72.00 Open glade  80.00 Set Basalt Stone 14 x 12 x 4 on S.E. face of mountain in mound of stone for Corner to Sec. 1, 12, 6 & 7.  A Pine, 10 ins. in diam., bears N.18° E. 51 Lks. dist.  " " 18 " " " S.70° E. 107" "  "Fir 14 " " " S.74° W. 160" "  No other trees  Land; surface, mountainous. Soil, 3rd rate & worthless.  Some good timber in places, but mostly scattering Tamarack  Fir and Fine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  40.00 Set Fir post on level for \$\frac{1}{2}\$ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.	- 32	April 19, 1879
Enter timber, East & West  Leave " " " "  30.00  36.00  Brook, 8 Lks. wide, course West  A Fir, 7 ins. in diam. on S.W.hillside for \$\frac{1}{2}\$ Sec. Corner  A Fir, 12 ins. in diam., bears S.70° E. 25 Lks.distant  " " 6 " " " " S.72° W. 8 " "  44.50  72.00  60.00  Copen glade  Set Basalt Stone 14 x 12 x 4 on S.E. face of mountain in mound of stone for Corner to Sec. 1, 12, 6 & 7.  A Pine, 10 ins. in diam., bears N.18° E. 51 Lks. dist.  " " 18 " " " S.70° E. 107" "  " Fir 14 " " " S.74° W. 160" "  No other trees  Land; surface, mountainous. Soil, 3rd rate & worthless.  Some good timber in places, but mostly scattering Tamarack  Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00  40.00  Enter timber, course E. & W.  Set Fir post on level for \$\frac{1}{2}\$ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.		North on the East Boundary of Section 12
Leave " " " " "  Brook, 8 Lks. wide, course West  A Fir, 7 ins. in diam. on S.W.hillside for \( \frac{1}{2} \) Sec. Corner  A Fir, 12 ins. in diam., bears S.70° E. 25 Lks.distant  " " 6 " " " " \$.72° W. 8 " "  44.50  Prook, 25 Lks. wide, course S.W.  Open glade  Set Basalt Stone 14 x 12 x 4 on S.E. face of mountain in mound of stone for Corner to Sec. 1, 12, 6 & 7.  A Pine, 10 ins. in diam., bears N.18° E. 51 Lks. dist.  " " 18 " " " \$.70° E. 107 " "  " Fir 14 " " " \$.74° W. 160 " "  No other trees  Land; surface, mountainous. Soil, 3rd rate & worthless.  Some good timber in places, but mostly scattering Tamarack  Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00  Enter timber, course E. & W.  Set Fir post on level for \( \frac{1}{4} \) Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.		Var. 18° 30' East
30.00 Enter " " " " "  36.00 Brook, 8 Lks. wide, course West  40.00 A Fir, 7 ins. in diam. on S.W.hillside for \$\frac{1}{2}\$ Sec. Corner  A Fir, 12 ins. in diam., bears S.70° E. 25 Lks.distant  " " 6 " " " " S.72° W. 8 " "  44.50 Brook, 25 Lks. wide, course S.W.  Open glade  80.00 Set Basalt Stone 14 x 12 x 4 on S.E. face of mountain in mound of stone for Corner to Sec. 1, 12, 6 & 7.  A Pine, 10 ins. in diam., bears N.18° E. 51 Lks. dist.  " " 18 " " " S.70° E. 107 " "  " Fir 14 " " " S.74° W. 160 " "  No other trees  Land; surface, mountainous. Soil, 3rd rate & worthless.  Some good timber in places, but mostly scattering Tamarack  Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  Set Fir post on level for \$\frac{1}{4}\$ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.	12.0	Enter timber, East & West
Brook, 8 Lks. wide, course West  A Fir, 7 ins. in diam. on S.W.hillside for \$\frac{1}{4}\$ Sec. Corner  A Fir, 12 ins. in diam., bears S.70° E. 25 Lks.distant  " " 6 " " " " S.72° W. 8 " "  Brook, 25 Lks. wide, course S.W.  Open glade  Set Basalt Stone 14 x 12 x 4 on S.E. face of mountain in mound of stone for Corner to Sec. 1, 12, 6 & 7.  A Pine, 10 ins. in diam., bears N.18° E. 51 Lks. dist.  " " 18 " " " S.70° E. 107 " "  " Fir 14 " " " S.74° W. 160 " "  No other trees  Land; surface, mountainous. Soil, 3rd rate & worthless.  Some good timber in places, but mostly scattering Tamarack  Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00  Enter timber, course E. & W.  Set Fir post on level for \$\frac{1}{4}\$ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.	20.0	O Leave " " " "
A Fir, 7 ins. in diam. on S.W.hillside for \$\frac{1}{2}\$ Sec. Corner  A Fir, 12 ins. in diam., bears S.70° E. 25 Lks.distant  " " 6 " " " " S.72° W. 8 " "  44.50 Brook, 25 Lks. wide, course S.W.  Open glade  80.00 Set Basalt Stone 14 x 12 x 4 on S.E. face of mountain in mound of stone for Corner to Sec. 1, 12, 6 & 7.  A Pine, 10 ins. in diam., bears N.18° E. 51 Lks. dist.  " " 18 " " " S.70° E. 107 " "  " Fir 14 " " " S.74° W. 160 " "  No other trees  Land; surface, mountainous. Soil, 3rd rate & worthless.  Some good timber in places, but mostly scattering Tamarack  Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  Set Fir post on level for \$\frac{1}{2}\$ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.	30.0	O Enter " " " "
A Fir, 12 ins. in diam., bears S.70° E. 25 Lks.distant " " 6 " " " S.72° W. 8 " "  44.50 Brook, 25 Lks. wide, course S.W.  72.00 Open glade 80.00 Set Basalt Stone 14 x 12 x 4 on S.E. face of mountain in mound of stone for Corner to Sec. 1, 12, 6 & 7.  A Pine, 10 ins. in diam., bears N.18° E. 51 Lks. dist. " " 18 " " " S.70° E. 107" " " Fir 14 " " " " S.74° W. 160" "  No other trees  Land; surface, mountainous. Soil, 3rd rate & worthless.  Some good timber in places, but mostly scattering Tamarack Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  Set Fir post on level for \$ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.	36.0	0 Brook, 8 Lks. wide, course West
Brook, 25 Lks. wide, course S.W.  Open glade  So.00 Set Basalt Stone 14 x 12 x 4 on S.E. face of mountain in mound of stone for Corner to Sec. 1, 12, 6 & 7.  A Pine, 10 ins. in diam., bears N.18° E. 51 Lks. dist.  "" 18 "" " S.70° E. 107" "  "Fir 14 "" " " S.74° W. 160" "  No other trees  Land; surface, mountainous. Soil, 3rd rate & worthless.  Some good timber in places, but mostly scattering Tamarack  Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  40.00 Set Fir post on level for \$\frac{1}{2}\$ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.	40.0	0 A Fir, 7 ins. in diam. on S.W.hillside for \( \frac{1}{4} \) Sec. Corner
Brook, 25 Lks. wide, course S.W.  Open glade  So.00 Set Basalt Stone 14 x 12 x 4 on S.E. face of mountain in mound of stone for Corner to Sec. 1, 12, 6 & 7.  A Pine, 10 ins. in diam., bears N.18° E. 51 Lks. dist.  "" 18 "" " S.70° E. 107" "  "Fir 14 "" " " S.74° W. 160" "  No other trees  Land; surface, mountainous. Soil, 3rd rate & worthless.  Some good timber in places, but mostly scattering Tamarack  Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  40.00 Set Fir post on level for \$\frac{1}{2}\$ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.		A Fir, 12 ins. in diam., bears S.70° E. 25 Lks.distant
Open glade  80.00 Set Basalt Stone 14 x 12 x 4 on S.E. face of mountain in mound of stone for Corner to Sec. 1, 12, 6 & 7.  A Pine, 10 ins. in diam., bears N.18° E. 51 Lks. dist.  " " 18 " " " S.70° E. 107 " "  " Fir 14 " " " " S.74° W. 160 " "  No other trees  Land; surface, mountainous. Soil, 3rd rate & worthless.  Some good timber in places, but mostly scattering Tamarack  Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  40.00 Set Fir post on level for \$\frac{1}{2}\$ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.		" " 6 " " " " S.72° W. 8 " "
Open glade  80.00 Set Basalt Stone 14 x 12 x 4 on S.E. face of mountain in mound of stone for Corner to Sec. 1, 12, 6 & 7.  A Pine, 10 ins. in diam., bears N.18° E. 51 Lks. dist.  " " 18 " " " S.70° E. 107 " "  " Fir 14 " " " " S.74° W. 160 " "  No other trees  Land; surface, mountainous. Soil, 3rd rate & worthless.  Some good timber in places, but mostly scattering Tamarack  Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  40.00 Set Fir post on level for \$\frac{1}{2}\$ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.	44.5	Brook, 25 Lks. wide, course S.W.
Set Basalt Stone 14 x 12 x 4 on S.E. face of mountain in mound of stone for Corner to Sec. 1, 12, 6 & 7.  A Pine, 10 ins. in diam., bears N.18° E. 51 Lks. dist.  " " 18 " " " S.70° E. 107 " "  " Fir 14 " " " S.74° W. 160 " "  No other trees  Land; surface, mountainous. Soil, 3rd rate & worthless.  Some good timber in places, but mostly scattering Tamarack  Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  Set Fir post on level for \$ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.	72.0	
mound of stone for Corner to Sec. 1, 12, 6 & 7.  A Pine, 10 ins. in diam., bears N.18° E. 51 Lks. dist.  " " 18 " " " " \$5.70° E. 107 " "  " Fir 14 " " " \$5.74° W. 160 " "  No other trees  Land; surface, mountainous. Soil, 3rd rate & worthless.  Some good timber in places, but mostly scattering Tamarack  Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  Set Fir post on level for \$\frac{1}{4}\$ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.	1	
A Pine, 10 ins. in diam., bears N.18° E. 51 Lks. dist.  " " 18 " " " " \$.70° E. 107 " "  " Fir 14 " " " " \$.74° W. 160 " "  No other trees  Land; surface, mountainous. Soil, 3rd rate & worthless.  Some good timber in places, but mostly scattering Tamarack  Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  40.00 Set Fir post on level for ½ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.		5
" " 18 " " " " S.70° E. 107 " "  "Fir 14 " " " " S.74° W. 160 " "  No other trees  Land; surface, mountainous. Soil, 3rd rate & worthless.  Some good timber in places, but mostly scattering Tamarack  Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  40.00 Set Fir post on level for ½ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.		
No other trees  Land; surface, mountainous. Soil, 3rd rate & worthless.  Some good timber in places, but mostly scattering Tamarack  Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  40.00 Set Fir post on level for \$\frac{1}{2}\$ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.		
No other trees  Land; surface, mountainous. Soil, 3rd rate & worthless.  Some good timber in places, but mostly scattering Tamarack  Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  40.00 Set Fir post on level for ½ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.		
Land; surface, mountainous. Soil, 3rd rate & worthless.  Some good timber in places, but mostly scattering Tamarack  Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  40.00 Set Fir post on level for 4 Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.		
Some good timber in places, but mostly scattering Tamarack Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  40.00 Set Fir post on level for ½ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.	8	
Fir and Pine.  April 22, 1879.  North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  40.00 Set Fir post on level for ½ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.		
North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  40.00 Set Fir post on level for ½ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.		
North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  40.00 Set Fir post on level for ½ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.		
North on the East Boundary of Section 1  Var. 19° 15' East.  8.00 Enter timber, course E. & W.  40.00 Set Fir post on level for ½ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.	1 *-	
Var. 19° 15' East.  8.00 Enter timber, course E. & W.  40.00 Set Fir post on level for ½ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.		
8.00 Enter timber, course E. & W.  40.00 Set Fir post on level for ½ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.		North on the East Boundary of Section 1
40.00 Set Fir post on level for \$\frac{1}{4}\$ Sec. Corner.  A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.		Var. 19° 15' East.
A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.	8.00	Enter timber, course E. & W.
H S	40.00	Set Fir post on level for 4 Sec. Corner.
11.62		A Spruce, 10 ins. in diam., bears N.84°E. 49 Lks.dist.
A Fir 28 " " " S.60°W. 13 " "	# 8	A Fir 28 " " " S.60°W. 13 " "