

## South Bdy. Tp.3 N., R.38 E.,W.M.

Chains		
10.50	Enter timber,S.E. & N.W.	
27.500	Brook, 10 lks. wide, course S.E.	-400
40.00	A fir, 10 ins. diam., on W. face of spur for $\frac{1}{4}$ Sec. Cor.	+300
	A fir, 12 ins. diam.,brs.N.70 lks. distant.	
	A pine, 16 ins. diam.,brs. S.12° W.,35 lks. distant.	
44.00	On spur,extends South	+50
80.00	Set Basalt Stone, 18 x 12. x 5 on S.E. face of spur for Cor.	
	to Secs. 35,36, 1 and 2.	
	A fir, 14 ins. diam.,brs.N.64°W.,94 lks. distant.	
	A fir, 8 ins. diam.,brs. N.30° E.,212 lks. distant.	
	No other trees.	
	Land; surface very broken and mountainous.	
	Soil; 3rd rate and worthless.	
	Scattering fir,pine and tamarack timber.	

East on the S.Bdy. of Sec.36.

Var. 18° 00' E.

26.50	Spring branch, course S.	
40.00	Set pine post on S.E. slope for $\frac{1}{4}$ Sec. Cor.	
	A pine, 20 ins. diam., brs. S. 63 lks. distant.	
	No other trees near.	
	Irregular broken descent.	
80.00	Set Basalt Stone, 18 x 8 x 6 on S.E. point of spur for	
	Cor. to Tps. 3 & 4 N.,Rs. 38 & 39 E.	
	A fir, 14 ins. diam., brs. N.56° E.,98 lks. distant.	
	A pine, 12 ins. diam.,brs. S.44 ° E.,110 lks. distant.	
	A pine, 15 ins. diam., brs. S.58° W.,95 lks. distant.	
	A fir, 10 ins. diam.,brs. N.38° W.,108 lks. distant.	
	Land; surface very broken and mountainous.	
	Soil; 3rd rate and worthless.	
	Scattering fir, tamarack and pine timber.	
	Dense underbrush.	

South Bdy. of Tp. 3 N.,R.38 E.  
 Executed by Jacob C. Cooper under Contract No. 397.  
 Dated July 14th, 1881.