Retracement of S. Bdy. of T.3 N., R.38 E., W. M. As surveyed by John W. Kimbrell, U.S. Deputy Surveyor, Under Contract LNo. 25700, Sdated Feb. 39th, 1899.

= 30 tas	- Marian Idan	
	Chains	From the Cor. to Secs. 1, 2, 11 & 12,T.3 N.,R.38 E.,I run
		N.1'W. bet. Secs. 1 & 2, and at
	70.75	Intersect N. Bdy., 52 lks. W. of old Closing Cor. of Secs.
	1	1 & 2, which I destroy, & 353 lks. W. of the 4 Sec.Cor.
548		on S. Bdy. of Sec.36, T.4 N., R.38 E., which is a post,
	4	decayed, markedd& witnessed, as described by the Sur'r
		General.
		I re-establish lt, as follows:
		Set granite stone, 20 x 8 x 3 ins., 14 ins. in ground, for
		\$ Sec. Cor. on S. Bdy., Sec.36, marked \$\frac{1}{4}\$ on N. face.
	9	I proceed to established Cor. to Secs. 35 & 36 on S. Bdy.
	811	of T.4 N., R.38 E., which is a stone, marked & witnessed
		as described by the Surveyor General.
	10 10	The bearing tree in Sec. 36 has fallen down & decayed. I
	til til	destrow all marks on it & mark a fir, 40 ins. diam., bts.
		N.21°E.,209 1ks. dist., marked T.4 N., R.38 E., S.36, B.T.
8	183	Thence I run
	94.0 404	E. on S. Bdy. of Sec. 36.
8	27.50	Spring branch, 2 lks. wide, course S.
3 8	36.97	The Closing Cor. to Secs. 1 & 2.
	40.50	The 4 Sec. Cor. on S. Bdy. of Sec. 36.
* +	80.50	The Cor. of T.4 N., R.38 E & 39 E., which is a stone, marked
		and witnessed as described by the Surveyor General.
		Land; mountainous.
		Soil; 4th rate, poor & rocky.
		Timber; fir, pine & tamarack.
		Dense undergrowth, willow & alder.
	4 1	Mountainous land, 80.50 chs.
1		Retracement of S. Bdy., T.4 N., R.39 E., W. M. As surveyed by the same U.S. deputy Surveyor, Under the same Contract and date.
	areas x	From the Con to III A N Do II C . TO T
		From the Cor. to T.4 N., Rs. 38 & 39 E., I run
	7 50	E. bet. Secs. 1 & 31.
	7.50	Spring branch, 3 lks. wide, course S.
	39.99	Intersect 15 lks. N. of established Cor. of T.3 N., Rs. 38 and 39 E., which is a post, in mound of stone, marked