Exterior Bdy. of T 5 N R 35 E., W.M. (E. Bdy.)

		it some second and the second and th
	Chains	
	67.25	Intersected the First Standard Parallel N., 888 chs. W.
	S	of post Cor., for T 5 N., R. 35 & 36 E.; set closing
		Cor. for T 4 N Rs. 35 & 36, Secs. 1 & 6, drove charred
	120.00	stake, dug pits and raised mound as per instructions.
89	0.8	Land; broken, grass excellent
		Soil; good 2nd rate.
		Subdivisional Lines of T. 4 N., R. 35 E., W.M. As surveyed by Wm. H. Odell, U.S. Deputy Surveyor Under Contract No. 114 Dated July 2nd, 1866.
		Commenced the survey of said subdivision line, August 18,
		1866. From the Cor to Secs. 1, 2, 35 & 36 on S. Bdy.
		of Tp. I run
		N. bet, Secs. 35 & 36
	4.70	Pine Creek, 10 lks. wide, course N.W.
	40.00	Set post Cor. for $\frac{1}{4}$ Sec. on steep hillside facing the N.
		drove charred stake, dug pits and raised mound as per
×		instructions.
	42.00	Small spring branch, course W.
	80.00	Set post Cor. for Secs. 25, 26, 35 & 36 on hillside facing
	. 47	and the state of t
	55 T	the S.W.; drove charred stake, raised mound of stone as per instructions.
	**	Land; broken, good grass
		Soil; 2nd rate.
		boil, and rate.
	-	The conversal of the co
		E. on random bet. Secs. 25 & 36
1	40.00	Var. 21° E.
	40.00	Set temp. ½ Sec. post Cor.
	80.10	Intersected N. & S. line, 40 lks. S. of post Cor.
	MANUAL PROPERTY.	S. 89° 43' W. on true line
	40.05	Set post Cor. for \(\frac{1}{4} \) Sec.; drove charred stake, dug pits
	25 02 (C-111012)	and raised mound as per instructions.
	80.10	To post Cor.
		Land; broken, good grass
		Soil; 2nd rate.