Chains	
	For meander Cor. bet. Secs. 19 & 30 and 19th mile post
*	I found the earth mound almost gone with pits filled
	up and post gone, destroyed by road and overflow of
	Wild Horse Creek.
	From point of meander Cor. bet. Secs. 29 & 30, pits &
	mound show plainly, but stone taken out and gone. I
	went S. bet. Secs. 29 & 30, I found \(\frac{1}{4} \) Sec. marked \(\frac{1}{4} \)
100	S. on side of post 3 ft. long by 3 ins. sq. on plowed
# 1	ground, pits and mound destroyed, Sec. Cor.
	Secs. 29 & 30, 31 & 32 plowed up and gone. Passing S. to
	Tp. line. I find some of the posts or stake on the plow
	ground, but no signs of pits or mounds. All destroyed.
	Service, and the service of the serv
	Sub-subdirited and of M A N D ZE D W M (A22-1
18	Sub-subdivisions of T 4 N R 35 E., W.M. (Allotments) As surveyed by survyeors, same, Contract & date.
	G
	Survey commenced on Oct. 13th, 1887.
	E. on random down through S. 2 of Sec. 32, T 4 N R 35 E.
100	Var. 20° E.
	Commencing at 1/16 Sec. Cor. 20.00 chs.
2,226.0	S. of \(\frac{1}{4} \) Sec. Cor., bet. Secs. 31 & 32
9 - 9 -	Set temp. Cors. at 20, 40 & 60 chs. and at
80.48	Intersect E. Bdy., 70 lks. N. of 1/16 Sec. Cor., thence
	N. 89° 30' W. on true line
20.12	Deposited charred stake, 12 ins. in the ground for 1/16
	Sec. Cor.; dug pits, 18 x 18 x 12 ins. E. & W. of stake
12	$5\frac{1}{2}$ ft. dist., raised mound of earth, $1\frac{1}{2}$ ft. high, $3\frac{1}{2}$
	ft. base over it and in E. pit; drove stake, 2 ft. long
	2 ins. sq., 12 ins. in the ground, marked 1/16 S. on
Mary 1	N. face.
40.84	1
40.24	Deposited charred stake, 12 ins. in the ground for 1/16
5.000	Sec. Cor., dug pits, 18 x 18 x 12 ins. E. & W. of stake
	$5\frac{1}{2}$ ft. dist., raised mound of earth, $1\frac{1}{2}$ ft. high, $3\frac{1}{2}$
111 0 1	ft. base over it and in E. pit; drove stake, 2 ft. long,
. 2	2 ins. sq., 12 ins. in the ground, marked 1/16 S. on
	N. face.
60.36	Depostied charred stake, 12 ins. in the ground for 1/16