1	Cheter	I ve
	Chains	F
	21.50	In gulch, course S.W.
	39.00	On spur, extending W.
- 19	40.00	Set basalt stone on N. side of ridge for \$\frac{1}{4}\$ Sec. Cor.
10.1	46.00	In gulch, opens W.
	66.50	Fence and field, course N.W. and S.E.
	76.40	Intersected 1st standard Parallel N. 14.60 chs. W. of
		standard Cor. to Secs. 34 & 35
- 1		Set fir post at point of intersection on S. slope in
		mound of stone in field, for Cor. to Secs. 2 & 3.
	3. 38	Land; surface, mountainous
		Soil; 3rd and 2nd rate.
		Good grass.
		Some good farming land; about 2/3 of Sec. 2 is well timbere
		At this standard Cor. the post was gone and but no witness
		tree left, the others were cut down.
		N. bet. Secs. 3 & 4
		AND TOTAL CONTRACTOR AND
		Var. 22° 00' E. Across small spurs and ravines
	40.00	2 2 22 4
	10.00	Set baslat stone, 16 x 12 x 4 on steep S. face of ridge
<i>a</i> 1	71.00	for ½ Sec. Cor.
		On ridge extending, E. & W.
	77.46	Set basalt stone, 14 x 10 x 5 on steep N. side, of ridge
-		at intersection of 1st Standard Parallel N. for Cor. to
		Secs. 3 & 4. 1432 chs. W. of standard Cor. to Secs. 33 &
		34, also set post in mound of stone.
		Land; surface mountainous
		Soil; 3rd rate. Good grass, valuable only for grazing.
	4	August 23rd, 1879.
-	*	Note: - after long and diligent search I could not find
=	RE	no trace of mounument for Standard Cor. to Secs. 33 &
		34, which I therefore proceed to re-establish.
		B (Se)
	¥-	W. on a random line bet. Secs. 21 & 28
8		