Chains	
	Land; surface undulating
	Soil; 2nd and 3rd rate. Good grass. Some scattering pine
N II	timber. Some good farming land.
	Tana.
(i)	N. on the E. Bdy. of Sec. 1
	Var. 20° 45' E.
40.00	Set basalt stone, 16 x 12 x 4, on level in mound of stone
	for ½ Sec. Cor.
54.50	A brook, 30 lks. wide, course N.W. and deep canyon
80.00	Set Pine post, 5 ins. sq. and 5 ft. long in mound of stone
	on level for Cor. to Tps. 4 and 5 S., Rs. 32 and 33 E.
	No trees near.
	Land; surface slightly undulating, except brook canyon
E	Soil; 3rd and 2nd rate. heavy Pine, Tamarack and Fir timbe
	in canyon. Good grass on prairie.
· .	May 30, 1881.
40	Note: - Took observation on Polaris, upon trial, my compass
	indicates an error 8' W. of meridian.
1 1	
71 (87 K	Subdivisional Lines of T. 5 S., R. 32 E., W.M. As surfeyed by, George S. Pershin, U.S. Deputy Surveyor, Under Contract No. 390, Dated May 12, 1881.
	N. bet. Sec. 35 & 36
	Var. 18° 45' E.
34	A Tamarack, 24 ins. diam. brs. N. 46° E., 30 lks, dist
40.00	Set basalt stone, 17 x 12 x 5 on slight N. slope for 1
10.00	Sec. Cor.
9 614	
	A Pine, 15 ins. diam. brs. N. 85° E., 28 lks. dist.
570 500	A Pige, 20 ins. diam. brs. S. 84° W., 81 lks. dist.
43.00	Spring brench, course N.W.
48100	Leave timber, course S.E. and N.W.
80.00	Set basalt stone, 24 x 12 x 5, and post in mound of stone
- A	on slight W. slope for Cor. to Sec. 25, 26, 35 and 36.
	Land; surface undulating,