Resurvey W. Bdy., T.5 S., R.33 E., W. M.

Cha	marked T.5 S.,R.33 E.,S.25,B.T.
	Destroyed marksdreferring to Secs. 30 & 31.
26	.00 Top of ridge, 100 ft. above Cor. to Secs. 30 & 31.
	50 The 4 Sec. Cor.
	.55 Creek, 20 lks. wide, runs N.W., in ravine, 300 ft. deep.
	And ascend.
80	.00 Set basalt stone, 24 x 12 x 6 ins., 18 ins. in ground, for
	Cor. to Secs. 22 & 27, marked with 2 notches on S. and
	4 ntoches on N. edges, with mound of stone alongside.
	Land; mountainous.
	Soil; 2nd & 3rd rate.
	Heavily timbered with pine, fir & tamarack.
	N. on W. Bdy. of Sec. 22.
	Var.19°20'E.
16	20 The Cor. to Secs. 24 & 25, which is a basalt stone, 20 x
	12 x 10 ins., marked with 4 notches on N. and 2 notches
	on S. edges, with mound of stone alongside, from which,
	A pine, 18 ins. diam., brs. N.46°E., 245 lks. dist.,
	marked T.5 S.,R.33 E.,S.19,B.T.
	A pine, 12 ins. diam., brs. S.18°W., 158 lks. dist.,
	marked T.5 S., R.33 E., S.25, B.T.
	Destroyed marks referring to Sees. 19 & 30
52	.50 Enter open glade.
56	20 The ½ Sec. Cor.
68	.20 Spring branch, course N.W. Enter scattering timber.
80	.00 Set basalt stone, 18 x 12 x 6 ins., 12 ins. in ground, for
	Cor. to Secs. 15 & 22, marked with 3 notches on N.& S.
1	edges, from which
	A pine, 6 ins. diam., brs. N.18°E., 18 lks. dist.,
	marked T.5 S., R.33 E., S.15, B.T.
	And raised mound of stone alongside.
1.	Land; mountainous.
1	
	Soil; 2nd & 3rd rate.
	Heavily timbered with pine, fir & tamarack, partially dead-
	ened by fire. Oct.12, 1882.