

X

Resurvey W. Bdy., T.5 S., R.33 $\frac{1}{2}$  E., W. M.

	<b>Chains</b>	N. on W. Bdy. of Sec. 15.
		Var. 20°30'E.
15.80	The Cor. to Secs. 13 & 24, which is a basalt stone, 17 x 10 x 8, marked with 3 notches on N. & S. edges, from which,	A tamarack, 18 ins. diam., brs. N.34°E., 36 lks. dist., marked T.5 S., R.34 E., S.18, B.T. A tamarack, 7 ins. diam., brs. S.58°E., 33 lks. dist., marked T.5 S., R.34 E., S.19, B.T. A tamarack, 9 ins. diam., brs. S.42°W., 75 lks. dist., marked T.5 S., R.33 E., S.24, B.T. A tamarack, 10 ins. diam., brs. N.41°W., 96 lks. dist., marked T.5 S., R.33 E., S.13, B.T.
	Destroyed marks referring to Secs. 18 & 19;	
19.55	Spring branch runs N.10°E.	
23.80	Spring branch runs. N.E.	
25.80	Same " " N.15°W.	
55.50	The $\frac{1}{4}$ Sec. Cor.	
80.00	Marked a fir, 18 ins. diam., T.5 S., R.33 $\frac{1}{2}$ E. on E., S.10 on N. and S.15 on S. faces, with 4 notches on S. and 2 notches on N. faces, for Cor. to Secs. 10 & 15, from which	A pine, 24 ins. diam., brs. N.43°E., 40 lks. dist., marked T.5 S., R.33 $\frac{1}{2}$ E., S.10, B.T. A fir, 24 ins. diam., brs. S.52°E., 32 lks. dist., marked T.5 S., R.33 $\frac{1}{2}$ E., S.15, B.T.
	Land; broken hills.	
	Soil; 2nd & 3rd rate.	
	Heavily timbered with pine, fir & tamarack.	
	 N. on W. Bdy. of Sec. 10.	
		Var. 19°E.
15.20	The Cor. to Secs. 12 & 13, which is a basalt stone, 18 x 13 x 5, marked with 4 notches on S. and 2 notches on N. edges, from which	A pine, 15 ins. diam., brs. N.28°E., 21 lks. dist.,